## **ISURVEY &** REMONUMENTATION

APR 2 4 1995

Ottawa County Remonumentation

RECORDED

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 15 AM 11:51

Thereis Collinson

Ottawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY.MI
1. Public Land Survey	T <u>7N</u> R <u>13W</u> T R T R T R	<u>G-3</u>	
2. Property Controlling	S T R		
in Section	S T R		
<ol><li>Miscellaneous</li></ol>	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
4. Lot No,	Recorded Plat		A B C D E F G H I J K L )
Maurice J.			2 6 5 4 3 2 4 1 3
Rosema	Jan.	4 94	4 7 8 9 10 11 12
	, in a field survey on		5
	equirements of P.A. 74, Michigan P.A. o		6 18 17 16 15 14 13 13 13 13 13 13 13 13 13 13 13 13 13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			7 1 1 1 1 1 1 1
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			8 19 20 21 22 23 24
	with the rules of the Michigan Board of		9 1 1 1 1 2
Court of Law; established, expressed below:	re-established, monumented, re-m	onumented, recovered, found as	
•			10 30 29 28 27 26 25 11 1 1 1 1 1 1
on this certificate	corners, all in the same town and e.	d range, may be recorded	12 -31 32 33 34 35 36
A. Description of origina	I monument and accessories and	or subsequent restoration:	13
10 - 1838 by	Class 10	)76 mam I O D O	31 . 11 . 4000

G-

Clapp - 1976 per L.C.R.C.

Campbell - 1980 per

R. Whitcomb D.S.

rec. in L. 3, P. 86

L.C.R.C. rec. in L.

12" Beech - N10° E .11 ch.

(over)

4, P. 74 (over)

8" Walnut - S39° W .41 ch.

Englert - 1976 per L.C.R.C. Joiner - 1988 per

rec. in L. 3, P. 101

L.C.R.C. rec. in L.

(over)

L. 5, P. 327 (over)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found C.I. mon. 0.5' below grade

found P.K. nail in SW. side (cut off) Power pole - N45 W 45.52'

Found nail and tag in E. side Power pole - N22° W 48.84'

Found nail and tag in E. side wood sign post - N10° W 53.33'

I hereby accept this corner as a correct and accurate perpetuation position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position G-3

C.I. mon.

Set nail and remon. tag in SE. side 15" Maple - S73 W 92.50'

Set nail and remon. tag in SW. side (cut off) Power pole - N45 W

Set nail and remon. tag in E. side Power pole - N22°W 48.84'

Set nail and remon. tag in E. side wood sign post - N10° W 53.33'

P.A. 345 OTTAWA CO	UNTY
PEER APPROVED 18	194
PEER APPROVED	

Surveyor's Michigan License No.

ROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

MAURICE J. ROSEMA

SURVEYOR

Part A - continued Clapp - 1976 per L.C.R.C. rec. in L. 3, P. 86 Iron Power pole - N15°W 48.5' Tele. pole - S40°E 45.5'

Englert - 1976 per L.C.R.C. rec. in L. 3, P. 101 1" Pipe Power pole - SE. 45.32' Power pole - NNW. 48.50' Tele. pole - NW. 45.55'

Campbell - 1980 per L.C.R.C. rec. in L. 4, P. 74 1" Pipe Power pole - SE. 45.32' Power pole - NNW. 48.50' Tele. pole - NW. 45.55'

Joiner - 1988 per L.C.R.C. rec. in L. 5, P. 327
Iron bar
Power pole - NNW. 48.33'
Cut off Power pole - NW. 45.55'
Wood sign post - N. 53.31'
4" tree - NNE. 60.72'