

APR 2 4 1095

Ottawa County Remonumentation

RECORDED

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 15 AM 11: 53

For corners in

Ottawa (County)		Located In:	Corner Code ##			
1.	Public Land Survey	T _ 7N_R _ 13W	G-6			
	·	T R	Pa.			
		T R				
		T R				
2.	Property Controlling	S T R				
	in Section	S T R				
3.	Miscellaneous	S T R				

Colydia Ridinan REGISTER OF DEEDS OTTAWA COUNTY, MI

umber

		- F R "			1					
2.	Property Controlling	S T R _								
	in Section	\$ T R _								
3.	Miscellaneous	S T R _			, p,	naistar at	Daada	C4	::	h1
	Property in Sec.	S			n.	egister of	Deeds	Stamp	A FIR	3 N
4.	Lot No , F	Recorded Plat				— A D	C D		<b>6</b> 11	ı
						_ <u>^ °</u>			TT	╁
	Manual and T					2	<del> </del>	<del>-</del> -∤-	┿- ┋-	+
	Maurice J.					3	+	11	++	-
	Rosema		Oct. 19		94	4 _ 7_	-8-		16-	_
		, in a field survey on				5				
		quirements of P.A. 74, Michi				6				
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						7	'/-	1	15.	
Man:	ent manual of survey instru agement or by a decree of :	actions of the United State	is Department of the Int	erior, Bureau	of Land	8	1	1 1	+	十
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a							20-	21-	22-	+
Cou	rt of Law; established, r	e-established, monument	ted, re-monumented, r	recovered, fo	ound as	9		+	++	+
expr	essed below:					1030_	29-	28		4
NOT	E: Not more than 4 c	orners, all in the same t	town and range, may	be recorde	ed	11		11	$\perp \perp$	
	on this certificate.		, , , , , , , , , , , , , , , , , , , ,	,		1231_	32			
						13	\ i		1	
A. G-6	Description of original	monument and accesso	ries and/or subseque	ent restorati	on: `	13	•	-11		
GLO -	· 1838 by	VanKoote	en - 1972 per L	.C.R.C.	Rosema	- 1985	per i	C. C. F	t.c.	
R. Wh	nitcomb D.S.		L. 1, P. 765 (		(over)		T	_ , _ , , ,		

Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Found C.I. mon. (0.6' below grade)

10" Beech - N26° W .6 ch.

Found nail in E. side 24" Maple - N9° W 137.98"

Found nail in SE. side Power pole - S50°W 79.55'

12" Walnut - S1 1/2° W .22 ch. Englert - 1972 per L.C.R.C.

Found nail in SE. side Power pole - S57°E 102.73°

P.A. 345 OTTAWA COUNTY

I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

rec. in L. 1, P. 707 (over)

C.I. mon.

G-6

Set nail and remon. tag in E. side 24" Maple - N9°W 137.98'

Set nail and remon. tag in NW. side 13" Ash - S46°W 34.77'

Set nail and remon. tag in SE. side Power pole - S50°W 79.55'

Set nail and remon. tag in NE. side Power pole - S57°E 102.73'

MAURICE J. ROSEMA LAND SURVEYOR NO. ROFESSION

Dec. 10, 1994

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 Part A - continued
Englert - 1972 per L.C.R.C. rec. in L. 1, P. 765
T-iron
Nail in side Power pole - Sw. 79.50'
Nail in side T. pole - SSE. 98.73'
Nail in side Power pole - SE. 102.66'
Sq. spike in side 20" Maple - NNW. 137.97'

Englert - 1972 per L.C.R.C. rec. in L. 1, P. 707 1" pipe Power pole - SE. 102.68' T. pole - SSE. 98.3' Street sign - NW. 41.05' Centerline of 6" Balsam - W. 25.55'

Rosema - 1985 per L.C.R.C.
C.I. mon.
P.K. nail in SE. side Power pole - SW. 79.50'
P.K. nail in NE. side Power pole - SE. 102.66'
Nail in E. side 24" Maple - NNW. 137.91'
On centerline of gravel roads N., S., E.