

SURVEY & REMONUMENTATION

APR 24 1995

Ottawa County remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:49

D. J. Rosema
REGISTER OF DEEDS
OTTAWA COUNTY, MI

COMMISSION

For corners in

Ottawa

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|--------------------------|------------|
| 1. Public Land Survey | T <u>7N</u> R <u>13W</u> | <u>I-7</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Maurice J. Rosema, in a field survey on Jan. 3, 1994, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- | | | |
|--|---|--|
| I-7 Englert - 1972 per L.C.R.C. recorded in L. 1, P. 707 | Rosema - 1987 per L.C.R.C. recorded in L. 5, P. 282 | Joiner - 1990 per L.C.R.C. recorded in L. 6. P. 84 |
| 2" Capped pipe | 2" capped pipe | C.I.M. |
| 24" Maple - E. 49.6' | Nail in SW. side twin Maple - SE. 16.80' | Twin 18" Maple - SE. 16.85' |
| Twin Maple - SE. 16.45' | Nail in N. side 20" Maple - E. 49.58' | 22" Maple - E. 49.60' |
| 16" Maple - S. 58.6' | On N-S fence line, fence cor. 10' N. | 20" Hickory - N. 25.06' |
| | Nail in E. side 18" Hickory - N. 25.05' | 12" Maple - SSE. 58.55' |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- I-7
Found C.I. mon.
Found nail in E. side 23" Hickory - N13°E 25.07'
Found nail in SW. side 18" tw. Maple - S38°E 16.82'
Found spike in W. side 17" Maple - S5°E 58.55'
On N.-S. fence line, fence cor. 10' N.
- G.L.O. - 1838 signed by R. Whitcomb D.S.
20" W. Oak - N35°W .34 ch.
24" Pine - S79°E .18 ch.

PA. 345 OTTAWA COUNTY
PEER APPROVED 4/18/94
Robert E. Newell

I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- I-7
C.I. mon.
Set nail and remon. tag in E. side 23" Hickory - N13°E 25.07'
Set nail and remon. tag in SW. side 18" tw. Maple - S38°E 16.82'
Set nail and remon. tag in N. side 33" Maple - S86°E 49.60'
Set nail and remon. tag in W. side 17" Maple - S5°E 58.55'



Signed by *Maurice J. Rosema*
Surveyor's Michigan License No. 27459

Date April 18, 1994