

Surveyor's Michigan License N

APR 2 4 1995

Ottawa County Remonumentation

RECORDED

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Revised May 14, 1971 7.38 Revised Jan., 1981

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE 94 DEC 15 AM 11: 54

For corners in	Filing Require	ment of Act 74, Mich. I	P.A. 1970 Physicis Williams
Ottawa	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY, MI
(County)			OF MIDA COUNTY, PRI
Public Land Survey	T 7N R 13W	<u>K-10</u>	
	T R T R		
	T R		·
2. Property Controlling	\$ T R		
in Section 3. Miscellaneous	S T R S T R		Boolston of Doods Stores & File Number
Property in Sec.	S T R		Register of Deeds Stamp & File Number
4. Lat No , F	Recorded Plat		A B C D E F G H I J K L
5. Private Claims			2 5 5 5 5 5 5
Maurice J.			3
Rosema		ec. 9	94 4 7 8 9 10 11 12
	, in a field survey on		itioned
in lines 1 and 2 above were in	n conformance with regulations and	d rules therefore as required	in the 6 18 17 16 15 14 13
	uctions of the United States Departr a Court of Law and/or that the corner	•	
	th the rules of the Michigan Board of re-established,monumented,re-m		ee ola
expressed below:	e-established, mondinented, re-ili	onamerited, recovered, rou	10 30 29 28 27 26 25
	orners, all in the same town and	d range, may be recorded	<b>3</b> 11)
on this certificate.			12 31 32 33 34 35 36 13 13 13 14 15 15
A. Description of original	monument and accessories and	or subsequent restoratio	
LO - 1838 by	Englert - 1976 per	L.C.R.C. Glaza	- 1989 per L.C.R.C.
. Whitcomb	rec. in L. 3, P. 13		in L. 6, P. 1 (over)
et post			
" Pine - N75 W .69 c	h. Joiner - 1981 per I		
	rec. in L. 4, P. 29	(over)	
B. Description of corner e	vidence found and/or method a	pplied in restoring or rees	stablishing corner:
-10		•	
	take in mon. box, replac	ed with 3/4" x 2'	steel rod with
tandard remon. cap		ca with by the Arb	Stool for with
	e 13" Maple cluump - Ne		
	fence post - S62°W 43.		am a the graphs, if
ound nail in W. side	Power pole - S84°E 54.		P.A. 345 OTTAWA COUNTY
		q	EER APPROVED_12/12/44
hereby accept this	corner as a correct and	l accurate	Il a Maderalla
	osition of the original		Seeder D. 7/2/44
C. Description of monume	ent for corner and accessories e	stablished to perpetuate I	locating the position of the corner:
-10		•	
/4" x 2' steel rod w	ith standard remon. cap	in mon. box	STATE OF MICHIGAN
et nail and remon. t	ag in NE. side 13" Mapl	le clump - N63°W 44	4.05' MAURICE J.
	ag in N. side fence pos		ROSEMA * LAND *
et mail and remon. to	ag in N. side Power pol	le - S84 E 55.32'	
et mair and remon. ta	ag in NE. side 8" Ash -	- S55 E 44.69°	27459 E
			SURVEYOR NO. 27459
			SURVEYOR NO. 27459
Signed by 41 but	a de		Dec. 10, 1994
Cianadau M A /V MI	ルルス ス・しぶ別界	ン Date	

REMON LIBER 2 PAGE 438

Part A - continued
Englert - 1976 per L.C.R.C. rec. in L. 3, P. 138
T-iron
Power pole - E. 55.14'
Tw. Maple - NW. 78.00'
12" Maple - W. 55.41'

Joiner - 1981 per L.C.R.C. rec. in L. 4, P. 291 C.I. mon.
Fence post - SW. 43.63'
Tw. 12" Maple - WNW. 43.17'
Power pole - E. 54.68'

Glaza - 1989 per L.C.R.C. rec. inl. 6, P. 1
MVK rerod
Nail in N. side 12" Maple clump - N60°W 44.10'
Nail in N. side Power pole - E. 55.32'
Nail in NE. side fence post - S60°W 43.59'