## SURVEY & REMONUMENTATION

FEB 2 7 1998

## Ottawa County Remonumentation

For corners in	SECTION	Filing Requirement of Act 74, Mich. P.A. 1970
		•

	RECORDED 97 DEC -8 AMIL: 29
	97 DFC -8 AMIL: 29
T R T R T R T R T R T R T R T R T R T R	REGISTER OF DEEDS OTTAWA COUNTY, MI
<u> </u>	Register of Deeds Stamp & File Number
A. Description of original monument and accessories and/or subsequent restoration:  I-2  GLO - Mullett - 1837   LCRC per L. 5, P. 333 (1988)   LCRC per L. 4, P. 24 (1	A B C D E F G H I J K I  2
15" Ash S5°W 15 lks 15" Beech - N4°E 25 lks  1-iron Nail in S side fc post - W 0.30' Spk in cor. fc post - W 0.30' Nail/tag in E side tw 6" Apple - N 26.42' Nail/tag in E side fc post - S Steel fc post - S 15'  LCRC per L. 6, P. 213 (1992) - CI mon - 4" Apple - N 24.10'	<b>W</b> 0'
T-iron - E 54.68', fc post - W 6.50'  B. Description of corner evidence found and/or method applied in restoring or reestablishing corner	
I-2 Found C.I. monument Found reil in F side 57 A1. Not 101	45 OTTAWA COUNTY
I hereby accept this corner as a correct and accurate perpetuation of the position of the original corner.	
I-2 C.I. monument Set nail and remon. tag in E side 5" Apple - N4 W 24.10' Set nail and remon. tag in S side wood post - S86 W 0.35' Set nail and remon. tag in S side wood post - N85 W 6.65' Centerline of base of steel fc post - S78 E 69.70'	* MAURICE J.  * MAURICE J.  * ROSEMA  LAND  SURVEYOR  NO.  27459  **  **  **  **  **  **  **  **  **
igned by	