Ottawa County remonumentation

Filing

93 DEC	15	AÇ1	9:	28

RECORDED

CORNER RECORDATION CERTIFICATE	
Requirement of Act 74, Mich. P.A. 1970	I Potential in his house
	REGISTER OF DEEDS

	)ttawa (County)	Located In:	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY, MI			
1.	Public Land Survey	T7NR14W TR		SURVEY & REMONUMENTATION			
2	Property Controlling	T R T R S T R		JEC 0 5 2008			
۴.	in Section	S T R					
3.		S T R		Register of Deeds Stamp & File Number			
٠.	Property in Sec.	S T R		negister of Deeds Stamp & File Number			
4.	Lot No	, Recorded Plat		ARCDEEGHIJKII			
5.	Private Claims	<u></u>		—— <u>(                                  </u>			
			1	2 <del>-                                     </del>			
				3 + + + + + + + + + + + + + + + + + + +			
ı. N	Maurice J. Rosema	_ , in a field survey onJu	ıly 31,93	4 7 8 9 10 11 12			
do	hereby certify that under r	requirements of P.A. 74, Michigan P.A	. of 1970, the corner points mentio	ned 6 19 17 1 1 1 1			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the							
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							
ab	ove were in conformance	with the rules of the Michigan Board	of Land Surveyors or by a Decree	of a			
	urt of Law; established, pressed below:	, re-established, monumented, re-	monumented, recovered, found	l as			

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Exxel Engineering - 1974 per L.C.R.C. I-13 recorded in Liber 2, Page 501 1" iron Spike with blaze on side P. pole - NE 93.06' Face of 3" street sign - SE 30.40' P.K. nail in side T. pole - SW 46.20

on this certificate.

Joiner - 1981 per L.C.R.C. recorded Prein and Newhof - 1991 per in Liber 4, Page 104 C.I.M. P. pole - NE 77.84'
T. pole - SW 46.08'

.11" tree - SE 93,26' Blendon corner - W 18.35'

L.C.R.C. recorded in Liber 6, Page 152 C.I.M. Nail and tag in E side tw 12"

Elm - N20°W 111.10' 60d S side P. pole - N45°E

93.201 P.K. in N side P. pole - N65°E 77.921

Nail in NE side 18" Elm -S25°E 93.231

Nail in top of 6" post -S45°W 46.23'

Blendon corner - W 18.37

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-13 Found C.I. monument in mon. box Found Blendon corner (C.I. mon. in mon. box) - W 18.37'
Found nail in top of T. box - S45°W 46.33'
Found P.K. nail in NW side P. pole - N68°E 77.93'

> I hereby accept this corner as a correct and accurate perpetuation of the position of the original section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

27459

Set O.C. remon. cap in conc. above C.I. monument in monument box Set nail and O.C. remon. tag in W side 19" Elm - S27°E 93.26' Set nail and O.C. remon. tag in E side P. pole - S15W 140.78' Set nail and O.C. remon. tag in NW side P. pole - N68°E 77.93 Set nail and 0,C. remon. tag in top of T. box post - S45°W 46.33' Set nail and O.C. remon. tag in E side 13" quad. Elm - N15°W 111.17' On centerline of E-W bit. conc. road On centerline of gravel road to N Centerline of gravel road to S - W 10'

OF MICHIGAN MAURICE J. ROSEMA LAND SURVEYOR MĐ. 27459

Maurice J. Rosena -Surveyor's Michigan License No.

Surveyi

Date\_ September 3, 1993.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 197

REMON LIBER 1 PAGE 218

REVISED MAY 14, 1975 REVISED JAN., 1983