SURVEY & REMONUMENTATION

APR 2 5 1995

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

94 DEC -8 PH 12: 35

4. Lot No.

expressed below:

Set Post

Private Claims ___

For corners in COMMISSION

_____ , Recorded Plat __

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED -

Ottawa (County)		Located In: Robinson Twp.	Corner Code ##
i.	Public Land Survey	T <u>7N R 15W</u> T <u>R </u>	C-6 W 1/4 Corner Section 17
?.	Property Controlling in Section	T R S T R S T R	
3.	Miscellaneous Property in Sec.	S T R S T R	

Physical Ridenay REGISTER OF DEEDS OTTAWA COUNTY.MI

Register of Deeds Stamp & File Number

Carl P. Englert, in a field survey on April 20 , 19	94
Jo hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points in lines 1 and 2 above were in conformance with regulations and rules therefore as requir	entioned ed in the
current manual of survey instructions of the United States Department of the Interior, Burea Aanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines	
bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Dourt of Law; established, re-established, monumented, re-monumented, recovered,	ecree of a

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

 Description of original monument and accessories and/or subsequent restoration: C-6 1/4 corner common to Sections 17 & 18 Original gov't corner set May, 1832 L.C.R.C. Liber 3, Page 1947 Found Iron Pipe, Set Cast Iron

by Calvin Britain D.S.

Monument Inscribed "Ottawa County Section Corner" Maple 12" S62°E 20 Links 14" Red Pine NE 40.17 16" Red Pine ESE 32.30 22" Maple W 46.99 Power Pole WNW 47.44

16" N62OW 5 Links

(See Back of Page)

30" Maple 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-6 1/4 corner common to Sections 17 & 18

Found 4" Harrison Cast Iron Mon. 10" deep 9' +/- East of Road Centerline

Found 22" Maple W. 46.99' +/- (No Nail) Found P.P. W.N.W. 47.44' +/- (No Nail)

Found 30" Maple N.W. 56.78' +/- (No Nail)

P.A. 345 OTTAWA COUNTY PEER APPROVED 11/21/94

Sector D. Fleder

NW 56.78

10

11 12

Accepted as a careful and faithful perpetuation of the original position of the corner.

•C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6 1/4 corner common to Sections 17 & 18

4" Harrison Cast Iron Mon.

O.C. Remon. Tag & Nail in S.E. Side 24" Aspen S120E 103.72

O.C. Remon. Tag & Nail in N Side 15" Scotch Pine S790E 51.44'

O.C. Remon. Tag & Nail in N.E. Side 36" Maple N52°W 57.19'
O.C. Remon. Tag & Nail in S. Side 30" Maple N89°W 47.92'

Cut "X" in Conc. Culvert S65°W 31.10'

anumilining ME OF MICHIEL ENGLERT JR. **PROFESSIONAL** SURVEYOR No 18987 SONAL S WAL SOMETHING

Signed by Caul P. Suglant

FORM APPROVED BY MICHIGAN STATE BOARD OF LAN

Liber 1, Page 297
C-6 Found Angle Iron
Nail in Face of 18" Oak SE 27.06'
Nail in Face of 12" Pine NE 29.59'
Nail in Face of 18" Maple W 47.11'
Nail in Face of 12" Pine E 31.90'
Nail in Face of 12" Pine NE 39.84'

STATES #