SURVEY & REMONUMENTATION

APR 2 5 1995

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC -8 PM 12: 35

Physicis Klimow REGISTER OF DEEDS OTTAWA COUNTY.MI

For corners in COMMISSION			Filing Requirement of Act 74, Mich. I		
Ottawa (County)		Located In: Robinson Twp.	Corner Code ##		
1.	Public Land Survey		T _7N_ R _15W T R T R T R	C-10 W 1/4 Corner Section 29	
 3. 	Property Controlling in Section Miscellaneous Property in Sec.	s	T R T R _T R		

Register of Deeds Stamp & File Number

Carl P.	Englert,	in a field survey on _	March 17	19 _ 94	
hereby certi	fy that under req	uirements of P.A. 74, Mic	thigan P.A. of 1970, the co	rner points mentioned	

n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

 Description of original monument and accessories and/or subsequent restoration: L.C.R.C. Liber 4, Page 282 (1/5/82)

Found Iron Bar, Set C.I.M.

10

12

N.W. 37.60' P.P. N.E. 39.18' Guy Pole S.E. 39.55' St. Sign

C-10 1/4 corner common to Sections 29 & 30 Original gov't corner set May 1832 by Calvin Britain D.S.

__ , Recorded Plat _

Private Claims _

Set Post Tamarack 6" S87°E 12 Links Do

5" N60°W 9 Links

(See Back of Page)

Description of corner evidence found and/or method applied in restoring or reestablishing corner: C-10 1/4 corner common to Sections 29 &30

Found 4" Harrison Cast Iron Mon. with Broken Top Found N.W. 37.60' P.P.

Found N.E. 39.18' Guy Pole

P.A. 345 OTTAWA COUNTY

PEER APPROVED_11/21/9
Soldon D. Pledero

Accepted as a careful and faithful perpetuation of the original position of the corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-10 1/4 corner common to Sections 29 & 30.

4" Harrison Cast Iron Monument with Broken Top

O.C. Remon. Tag & Nail in W. Side P.P. S5^{OW} 327.12' O.C. Remon. Tag & Nail in N. Side P.P. N84^{OW} 352.58'

O.C. Remon. Tag & Nail in N.E. Side P.P. N430W 37.67' O.C. Remon. Tag & Nail in S.E. Side Guy P. N490E 39.26'

Monument in center of Intersection 6" deep

THE CARLP. ENGLERT JR. **PROFESSIONAL** SIONAL

Signed by Carl & England Surveyor's Michigan License No.

_____ Date _///21 /94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

A. Description of original monument and accessories and/or subsequent restoration.

C-10 L.C.R.C. Liber 2, Page 413 (11/30/73) Found 5/8" Rod N.W. 37.60' P.P. N.E. 39.18' Guy Pole S.E. 39.55' St. Sign