SURVEY & REMONUMENTATION

APR 2 5 1995

or corners in

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC -8 PM 12: 36

COMMISSION

Ottawa (County)	Located In: Robinson Twp.	Corner Code ##
Public Land Survey	T <u>7N</u> R <u>15W</u> T R T R T R	C-11 SW corner Section 29
Property Controlling in Section Miscellaneous	S T R S T R S T R	

Dhydie Calinan REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

Lot No. __ , Recorded Plat __ Private Claims __

March | 18 Carl P. Englert in a field survey on _ hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned fines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

C-11 corner common to Sections 29,30,31 and 32. Original gov't corner set a May 1832

by Calvin Britain D.S.

Set Corner

Tamarak 10" S59°E 1.14 chains

Do 4" S64°W 11 Links

LCRC Liber 2, Page 35 Set CIM from ties Angle Iron East 33' 10" Pine W.N.W. 75.03' P.P. S.S.W. 77.65' 10" Poplar N.N.E. 94.40' Fence Cor. Post E. 33.46'

10

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-11 corner common to Sections 29,30,31 and 32.

Found 4" Harrison Cast Iron Mon. with Broken Top 15" deep.

Found 10" Pine N.W. 75.03

Found P.P. S.S.W. 77.65'

Found Fence corner Post East 33.5! +/-

Accepted as a careful and faithful perpetuation of the position of the original corner.

P.A. 345 OTTAWA COUNTY

PEER APPROVED_

 Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-11 corner common to Sections 29,30,31 and 32.

4" Harrison C.I.M. with broken top

O.C. Remon. Tag & Nail in W. side P.P. NO50W 271.88'

O.C. Remon. Tag & Nail in S. side 14" Scotch Pine N820W 74.90'

O.C. Remon. Tag & Nail in W. side P.P. S190W 78.01' O.C. Remon. Tag & Nail in W. side P.P. S040W 419.42'

6: +/- West of the centerline of dirt road.



∎rveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LANS SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983