## SURVEY & REMONUMENTATION

APR 2 5 1995

OTTAWA COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

94 DEC -8 PM 12: 35

RECORDED

For corners in

COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

Sely-die Radinan

Ottawa (County)	Located In: Robinson Twp	Corner Code ##	REGISTER OF DEEDS OTTAWA COUNTY, MI
Public Land Survey	T <u>7N</u> R <u>15</u> W T R T R T R	D-13 S 1/4 Corner Section 32	·
2. Property Controlling	S T R		
in Section	S T R		
<ol><li>Miscellaneous</li></ol>	S R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
	, Recorded Plat		A B C D E F G H I J K L M
J. THEOLO SIGNIO			2 6 5 4 3 4 2
			3

Carl P. Englert, in a field survey on March 18 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

4. Description of original monument and accessories and/or subsequent restoration:

D-13 South 1/4 corner Section 32 Original gov't corner set May, 1832 by Calvin Britain D.S.

Tamarack 10" is Post

LCRC Liber 6, Page 145 Raised CIM Nail in P.P. S.E. 66.17' 16" Oak N.N.E. 44.28' 24" Maple W.S.W. 91.60'

Olive corner West 131.53'

(See Back of Page)

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-13 South 1/4 corner Section 32

Found 3" Harrison Cast Iron Mon. in Mon. Box.

Found P.P. S.E. 66.17'

Found 16" Oak N.N.E. 44.28'

Found 24" Maple W.S.W. 91.60'

Olive corner West 131.53'

Accepted as a careful and faithful perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-13 South 1/4 corner Section 32

3" Harrison C.I.M. in Mon. Box on pavement centerline

O.C. Remon. Tag & Nail in N.E. side P.P. S580E 66.13'

O.C. Remon. Tag & Nail in N.W. side 28" Maple S720W 91.51'

O.C. Remon. Tag & Nail in E. side 8" Oak N19°W 119.46'

O.C. Remon. Tag & Nail S.E. side 20" Oak N16°E 44.22'

Olive corner W. 131.53

OF MICHIG ENGLERT JR. **PROFESSIONAL** SURVEYOR 18987

Signed by Cal P. Englest 18987 Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 A. Description of original monument and accessories and/or subsequent restoration:

D-13 LCRC Liber 2, Page 37
Set C.I.M. in Place of Iron Pipe
9" Oak N.E. 53.62'
Centerline Street Sign N.E. 26.30'
P.P. S.E. 65.70'
20" Maple S.W. 90.26'
T.P. N.W. 97.54'

REMON LIBER 1 PAGE 499