## SURVEY & REMONUMENTATION

FEB 2 7 1998

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

						_	_
	~	$\sim$	$\cap$	R	n		П
H	-	١.	11	ĸ	1 1	r	1)
1.	_	v	v	٤,	$\sim$	-	_

SECTION For corners in

Ottawa

Corner Code # Located In: Robinson Township

97 OCT 30 AHII: 00

1. Public Land Survey

(County)

T7N R 15W 7 R

W 1/4 corner Section 25

2. Property Controlling in Section

3. Miscellaneous Property in Sec.


Register of Deeds Ottawa County, MI

Register of Deeds Stamp & File Number

\_, Recorded Plat\_ 5. Private Claims

I, Carl P. Englert, in a field survey on 3/3 \_, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

K-10 1/4 corner common to Sections 25 and 26

G.L.O. 1832 Calvin Britain

LCRC Liber 1, Pages 559 & 560

Set 1/2 Mile Post

K-10 Found Iron Set Cast Iron Monument

Maple 18" N41°E 25 links

28" Maple

SW 87.291

Hemlock 7" S30°W 8 links

10" Red Pine SE 78.85'

Fence Corner

NW 34.11'

Power Pole

SE 97.12'

(8-14-72)

See Other Side Street Sign Post SE 43.30'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-10 1/4 corner common to Sections 25 and 26

Found 4" Harrison Cast Iron Monument with Broken Top

Found P.P.

SE 97.12' (Nail in face)

P.A. 345 OTTAWA COUNTY

Found 15" Red Pine SE 78.85'

Found 36" Maple

SW 87<sup>±</sup> (No Nail)

PEER APPROVED 9-15-9

Accepted as a careful and faithful perpetuation of the position of the original corner.

С. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

K-10 1/4 corner common to Sections 25 and 26

4" Harrison Cast Iron Monument with Broken Top

4" Harrison Cast Iron Montament

O.C. Remon Tag & Nail in NW Side 36" Maple S520W 07.30

O.C. Remon Tag & Nail in SW Side 15" Red Pine S300E 79.05 C7.78 C7.

O.C. Remon Tag & Nail in W Side 8" Oak 4 Gravel Road is East 8 feet ±

OF MICHING **PROFESSIONAL** SURVEYOR Nα 18987 SONAL S

2.00

Surveyor's Michigan License No.

Robinson Township, Section 26, Town 7 North, Range 15 West Liber 3, Page 279
K-10
12" Red Pine S20°E 78.88'
Power Pole S80°E 97.23'
Triple 8" Maple N30°E 69.32' (7-26-78)

SURVEY & REMONUMENTATION

O

FEB 2 7 1998

**SECTION**