SURVEY & REMONUMENTATION

APR 2 4 1995

OTTAWA COUNTY REMONUMENTATION

RECORDED

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 15 AM 11: 46

For corners in

Ottawa Located In: Corner Code ## (County) K-12 (W¼, 36) T 8N R 13W 1. Public Land Survey T ____ R ____ Wright Twp. T ____ R __ T R __ _ T ____ R __ 2. Property Controlling in Section S ____ T .___ R _ Miscellaneous Property in Sec.

Physical Bellow REGISTER OF DEEDS OTTAWA COUNTY MI

Register of Deeds Stamp & File Number

4.	Lot No	, Recorded Plat	
5.	Private Claims		

November 29, Donald W. Schiele in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

A. Description of original monument and accessories and/or subsequent restoration:

K-12 ¼ corner common to Sections 35 & 36, Wright Twp.

Original Government Corner Record:

L.C.R.C. recorded in Liber 3, Page 95, 6-18-76 Iron in MB

Set qr sec post between Sec. 35 & 36

Post

SE cor hse

NW 90.981

S40W 18 S19E 20 16 Beech

PK in sde P. Pole

SW 60.92'

Do 10 PK in sde cor fe post East 27.37'

Enoch Hammele, Deputy Surveyor

Between 9-18 and 9-26, 1838

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

K-12 Found 2-3/4" dia. Cast Iron Monument (broken), 7" below surface in Monument Box, and accepted as a careful and faithful perpetuation of the position of the original corner.

S87°E 28.27'

OF MICHAEL CONTROLL CON

accepted as a caleful and larging be because	1011 01 0110	P
Found PK nail in North side of single Fence Post	S87°E	28.27
Found nail in NE side of Power Pole	S50°30'W	60.53'
Found PK nail in SE side of Power Pole	S50°30'W	60.99'
Found nail & MSHD Tag in NW side of Power Pole	S50°30'W	61.19'
SE frame corner to House # 14815	N56°W	90.93'
Found nail in SE side of Power Pole	N50°30'W	58.191
Found PK nail in NE side of Power Pole	N50°30'W	58.66'
TOURING THE STATE OF THE STATE		



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-12 Broken 2-3/4" dia. Cast Iron Monument, 7" below surface in Monument Box. Set Ottawa County Remon Tag & nail in North side of 16" Twin Maple East 175

Set Ottawa County Remon Tag & nail in NW side of Power Pole S50°30'W 61

175.43' 61.07'

SE frame corner to House # 14815

N56°W 90.931

Set Ottawa County Remon Tag & nail in East side of 17" Maple Centerline asphalt road North & South, 0.3' West Centerline asphalt road West, 1' South

N26°W 89.801

Fence line to East, 2' South

P.A. 345 OTTAWA COUNTY

Signed by .

Surveyor's Michigan License No. _

23517

v. Seli

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971