## OTTAWA COUNTY REMONUMENTATION

## RECORDED

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 16 PM 1:01

| E ~ = | 0010010 | in  |
|-------|---------|-----|
| POT   | corners | 111 |

| 0  | ttawa<br>(County)               | Located In: Polkton Townsh                 | Corner Code ##<br>ip            |
|----|---------------------------------|--|---------------------------------|
| 1. | Public Land Survey              | T <u>8N</u> R <u>14W</u> T R<br>T R<br>T R | A-11<br>SW Corner<br>Section 30 |
| 2. | Property Controlling in Section | S T R<br>S T R                             |                                 |
| 3. | Miscellaneous                   | S T R                                      |                                 |

Physicis Bademan REGISTER OF DEEDS OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

\_\_\_\_\_, Recorded Plat \_\_ 5. Private Claims \_

Carl P Englert Jr.

, in a field survey on August 6 , <sub>19</sub> <u>9</u>3 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines  ${\bf 3}, {\bf 4}$  and  ${\bf 5}$ above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L.C.R.C. Liber 3, Page 339, 2/20/79

Fd. 3/8" Rod

NE 50.14' 36" Maple

SE 48.72' T.P.

SW 47.91' Oak

W 41.10 24" Maple

L.C.R.C. Liber 4, Page 106, 10/14/80

Fd. 1" Iron pipe from old ties

Set C.I.M.

40" Maple NE 50.17'

T.P. SE 48.66'

30" Oak SW 47.87'

40" Oak WNW 29.86'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 4" Harrison Cast Iron Monument 8" Deep and accepted as a careful and faithful perpetuation of the position of the original corner.

T.P. SE 48.66' 36" Oak SW 47.89' 40" Maple NE 50.19'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 4" Harrison Cast Iron Monument

O.C. Remon. & Nail in SW side 36" Oak S 45 degrees W 47.88'

O.C. Remon. & Nail in S side 30" Maple W 41.50'
O.C. Remon. & Nail in NE side 17" Maple N 40 degrees W 44.50'

O.C. Remon. & Nail in NW side 40" Maple N 45 degrees E 50.50'

O.C. Remon. & Nail in NE side T.P. S 40 degrees E 48.72'

Tape

Date December 3, 1993

Signed by Carl P. Englant Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEY,

REVISED JAN

STORY OF MICHIGA

ENGLERT JR. LAND Surveyor

00000000000000000