## OTTAWA COUNTY REMONUMENTATION

## RECORDED

## LAND CORNER RECORDATION CERTIFICATE 93 DEC 16 PM 1: 01

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Delythis Colleman Ot<u>tawa</u> REGISTER OF DEEDS OTTAWA COUNTY, MI Located In: Corner Code ## T\_8N\_R\_14W G-9 (NE, 28) 1. Public Land Survey Polkton Twp. T \_\_\_\_\_ R \_\_\_\_\_ T \_\_\_\_ R \_\_ S \_\_\_ T \_\_\_ R \_\_\_ Property Controlling in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_\_\_ , Recorded Plat \_\_\_ Lot No. Private Claims \_ Donald W. Schiele in a field survey on \_ December 4, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: G-9 corner common to Sections 21, 22, 27 & 28, Polkton Twp. L.C.R.C. recorded in Liber 2, L.C.R.C. recorded in Liber 4, T.C.R.C. recorded in Liber 2, Page 625, 10-9-74 Iron and Stone L.C.R.C. recorded in Liber 5, Page 205, 5-3-85 Page 304, 4-1-82 C.I.M. C.I.M. S 50.90' P.P. C.L. Telephone Box NNW 25.5' Nail & B.C. in Power Pole 50.86 N.W. 43.67' P.P. Tele. Ped. NNW 25.571 N.E. 100.23' to S.E. Cor. bldg. W side P pole 82.521 SW Cor. Bldg. NNE 50.85 SE Cor. Bldg. SW cor of bldg 100.251 NE (cor of brick) NNE 82.42 Also: See L.C.R.C. recorded in Liber 2, Page 731, 1-14-75. SE cor of bldg B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (cor of brick) NE 100.22 G-9 Found Cast Iron Monument with top broken off 8" below surface in Monument Box 2" below surface of asphalt road and accepted as a careful and faithful perpetuation of the position of the original corner. SW corner brick veneer to Building # 7193 82.41' SE corner brick veneer to Building # 7193 100.121 50.91 Found PK nail in East side of Power Pole South Found nail & bottle cap in West side of Power Pole 50.90 South 25.54 Centerline Telephone Pedestal NNW NO6°W Found PK nail in East side of Power Pole

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9 Set 3/4" X 4" solid bar with Ottawa County Remon Cap over broken Cast Iron Monument,

2½" below surface in raised Monument Box. SW corner brick veneer to Building # 7193 N14°E 82.41' SE corner brick veneer to Building # 7193
SE corner brick veneer to Building # 7193
Set Ottawa County Remon Tag & nail in West side of Power Pole
Set Ottawa County Remon Tag & nail in East side of Power Pole
Pole line to North, 4' West
Centerline asphalt road East & West, 2' South N38°F 100.121 S01°W 50.90' N06°W 40.401 On centerline tangent line of asphalt road to West Donald W Land Surveyor \_\_\_\_ Date Dec. 6, 1993 FORM APPROVED BY MICHIGAN STATE BUAND DAYAND SURVEYORS MAN 1975 23517 Surveyor's Michigan License No. .