SURVEY & REMONUMENTATION

FFB 2 7 1998

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 30 AMII: 01

For corners in	aratic

Ottawa

1. Public Land Survey

SECTION Corner Code # Located In: Crockery

Township T<u>an</u> R<u>15W</u>

R 2. Property Controlling R

in Section R 3. Miscellaneous Property in Sec.

W 1/4 corner Section 5


Register of Deeds Ottāwa County, MI

Register of Deeds Stamp & File Number

, Recorded Plat 4. Lot No. 5. Private Claims

I, Carl P. Englert, in a field survey on 3/5 , 19 <u>9 7</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

C-2 1/4 corner common to Sections 5 & 6

G.L.O. 1837 John Mullett Set 1/4 Section Post Pine 20" S36°W 35 links W. Oak 18" N410E 7 links LCRC Liber 2, Page 337 (10/30/73)

Found 1/2" Pipe N35°W 32.27' Nail in Side of 17" Oak N200E 45.07' Nail in Face of 12" Oak

 $N40^{\circ}E$ 47.56' Nail in Side of 13" Oak

South 41.67' Nail in Side of P.P.

See Other Side

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

C-2 1/4 corner common to Sections 5 & 6

Found 4" Harrison Cast Iron Monument 8" deep 2' North of centerline Gravel Road

Found 17" Oak

N35°W 31.29'

Found 12" Oak

N20°E 45.05'

Found Power Pole South 41.18'

PEER APPROVED

PRISOUPING OF

Accepted as a careful and faithful perpetuation of the origina position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-2 1/4 corner common to Sections 5 & 6

4" Harrison Cast Iron Monument

O.C. Remon Tag & Nail in NW Side 16" Oak

N570E 68.87

W Side 20" Oak N 70E 49.93' O.C. Remon Tag & Nail in

O.C. Remon Tag & Nail in NW Side 7" Maple ·S51°W 63.06' O.C. Remon Tag & Nail in W Side Power Pole South 41.57

Surveyor's Michigan License No.

ENGLERT JR. PROFESSIONAL SURVEYOR 18987 SONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL

REVISED MAY 14,1975 REVISED JAN., 1983

C-2 Town 8 North, Range 15 West
LCRC Liber 3, Page 227
Replaced Iron Pipe with Cast Iron Monument inscribed
"Ottawa County Section Corner"
17" Oak N35°W 31.29'
12" Oak N20°E 45.05'
13" Oak N40°E 46.53'
Power Pole South 41.18'

SURVEY & REMONUMENTATION

FEB 2 7 1998

SECTION

11.00 CURNE

REMON LIBER 3 PAGE 560