## SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 BEC -8 PH 12: 37

For corners in			. 1310						st lighter
Ottawa (County)	Located In: Crockery Twp	Corner Code ##				PRE 01	EGISTI TTAWA	ER OF 1 COUR	DEEDS NTY. MI
Public Land Survey	T <u>8N</u> R 15W T R T R T R	J-5 S1/4 Corner Section 11							
<ol> <li>Property Controlling in Section</li> </ol>	S T R S T R								
Miscellaneous     Property in Sec.	S T R S T R		Register	of De	eds S	tamp &	k File	Numt	)er
4. Lot No , I	Recorded Plat			ъ.					
			<u>^</u>	Ť		E F 6	3 H		T T
			3	- 6 	_ 5		3 		$\pm 1$
Carl D Fraler	t March	16 04	4	- ?	8	-9-	10	<u> </u>	12
	thin a field survey on <u>March</u> quirements of P.A. 74, Michigan P.A. of		ed	╅	++	- -		+	+
	n conformance with regulations and ructions of the United States Department			-18 <del> </del>	<del>-17</del>	—16— 	15 	<del> -14-</del>	13-1
fanagement or by a decree of bove were in conformance w	a Court of Law and/or that the corner p ith the rules of the Michigan Board of L re-established, monumented, re-mo	points mentioned in lines 3, 4 and and Surveyors or by a Decree o	d5 a	19	20 	21		23	24
on this certificate			11 12 13	-31	32-	-33	34	35-	36
	monument and accessories and/o								

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-5 1/4 corner common to Sections 11 and 14.

Found 4" Cast Iron Monument with top broken off in mon. box Found Nail in P.P. NNW 24.62'

Accepted as a careful and faithful perpetuation of the position of the original corner.

LCRC Liber 2, Page 73 (3/23/73)

Fd. Cast Iron Monument P.P. NNW 24.62'

10" Pine NNE 57.67'

16" Cherry SE 34.95' Tel. Pole WSW 84.56'

							•
Э.	Description of monument for corner	and	acces	ssories	established	to perpetuate	locating the position of the corner:
			_				

J-5 1/4 corner common to Sections 11 and 14.

Original gov't corner set March 1837

by John Mullet Set Post

Beech 6" S72°E 10 Links

Do 9" N37°W 30 Links

4" Harrison C.I.M. with broken top in Monument Box O.C. Remon. Tag & Nail in NW side 40" Maple S44°W 81.32' O.C. Remon. Tag & Nail in W side P.P. N17°W 25.01'

O.C. Remon. Tag & Nail in N side 20" Ash S76°E 115.65'
O.C. Remon. Tag & Nail in SW side 22" Maple S40°E 53.88'
Centerline Top Bolt on fire hydrant North 44 degrees East 45.14'
Centerline pavement 3' +/- North

CARL P. ENGLERT IR **PROFESSIONAL** SURVEYOR No. 18987

Surveyor's Michigan License No

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED WAY 14, 1975