
DEC 01 1998

SECTION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

r		- ·····g ··	.oquitomonic or	74, WIOII.	1 17. 1070	,					
For (corners in Ottawa	Located In:	Corno	r Coda #	1	RECORDED					
	(County)	Locatod III,	Contro	Corner Code #		98 JUL 24 PM 1: 47					
2. F ii 3. N	Property Controlling S_n Section S_Miscellaneous S_Property in Sec. S_	T 8 N R 16 C T R T R T R T R T R T R T R T R	West Secti	1/4 corner on 17	Reg	REGISTER OF DEEDS OTTAWA COUNTY, MI Register of Deeds Stamp & File Number					
4. L	ot No, Recorde	ed Plat			<u> </u>	. A B C	DEF	G H			
I, Sido hi in lin curre Mane above Courre expre	Private Claims ereby certify that under requirer les 1 and 2 above were in con nt manual of survey instructions agement or by a decree of a Cou e were in conformance with the t of Law; established, re-es essed below: E: Not more than 4 corner on this certificate. Description of original more	May 19 9 the corner points merefore as require la Interior, Bureau nentioned in lines 3 urveyors or by a Deted, recovered, for may be recorded.	nentioned ed in the of Land 8, 4 and 5 ecree of a bound as	2 6 3 4 7 5 6 18 7 8 19 9 10 30 11 12 31 13		27	23 26	13 24 25			
	C-6 No information									-	
	GLO - Mullett - 1837 40.00 set quarter section post Pine 10 S 1 E 4.68 No other					PA. 345 CTTAWA COUNTY APPROVED 6-15-98 J.D.D.					
B.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:										
	C-6										
	Found no field evidence or survey record that the original GLO quarter section post had ever been located since the original GLO survey. Calculated the position of C-6 mid-way and on line between C-5 and C-7. Calculated position of C-6 is in a large active sand mining operation.										
	See sketch on back.										
	Calculated position of C-6 is accepted as a careful and faithful re-establishment of the position of the original corner.										
c.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:										
	C-6						NIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	Milling,	te.		
	Calculated position			ji.	MILITATE	VEN	William .				
	Azimuth = Michigan Stat			mm	T LAN	IPEN NO					
	Remonumentation tag in Remonumentation tag in Remonumentation tag in Remonumentation tag in	West side South side	14" Oak 20" Oak 32" Ash 6" Poplar	356° 24' 354° 08' 295° 19' 283° 31'	814.69 722.29 563.66 555.10	HIMMIN	STE LAM SURV	EYOR O. 279	100 MILLION		
Signe	ed by Sterran I	amoen.		Date J	10LY 20	S. 1998	: -नस्स्री		2		
_	eyor's Michigan License No.	17						ध	7		
-ui v (2701 0 morngan License NO.	<u> </u>		<u>_</u>	FORM APPRO	VED BY MICHIGAN	STATE BOARD OF	LAND SURVE	YORS, JAN	. 28, 19	



FOUND CAST IRON MONUHENT