FEB 2 4 2000

OTTAWA COUNTY REMONUMENTATION

RECORDED

SECTION

For corners in Ottawa

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

99 JUL 30 PM 12: 26

Panj	della
REGIST	ER OF DEEDS A COUNTY, MI

	Located in: Corner Code #		OTTAWA COUNTY, MI	
(County)	Chester Twp.			
	9N 13W	A-12 W 1/4 Cor.		
1. Public Land Survey	TR	Sec_31_		
	T R			
•	T R		-	
	T R			
2. Property Controlling	s T R			
in Section	s T R			
	s T R			
3. Miscellaneous	s T R			
Property in Sec.	S IK		Register of Deeds 3	Stamp & File Number
	•			
4.1.131				
	rded Plat		ABCDEF	G H I J K' L
5. Private Claims	· · · · · · · · · · · · · · · · · · ·		1	
			2 6 5 4-	
		00	3	
Randal D. Feenstra	March 10	99		
f,	, in a field survey on	, 19 do hereby state that under	4 - ? - 9 - 9 - 9 -	10-11-12
requirements of P & 74 Michia	ian P.A. of 1970, the corner points me	ntioned in lines 1 and 2 shows were in		

9 10 11

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded

conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

G.L.O. Not Set

recovered, found as expressed below:

on this certificate.

P-113 1990 (Joiner) L-6

A-12 Found Cast Iron Monument

SW Garage Cor. ENE 106.17 152.40 NW House Cor. NE 12" Cherry NW 82.96 4" Elm SW 50.70

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found: Broken Cast Iron Monument in Gravel A-12

Found NW House Cor. Found SW Garage Cor.

AZ 41°45'

106.11 AZ 81°30'

PAL 345 OTTAWA COUNTY PEER APPROVED 7/12

HICHIE

RANDAL D EENSTRA

LAND

NO.

SED LAND SU

This position not established by original government surveyors. This location is accepted as the best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Broken Cast Iron Monument in gravel (See Sketch)

NW Cor. House Foundation AZ 41°45'

SW Cor. Garage Foundation

AZ 81°30'

152.34' 106.11'

Rebar in gravel shoulder of road

AZ 315°30'

27.48'

NW Cor., Sec. 31

North

2638.94

Centerline N-S gravel Rd. (48th Ave.) West 3.5'

May 14, 1999

Date

37275 Surveyor's Michigan License No

FEB 2 4 2000

SECTION

