## BUHVEY & REMONUMENTATION

JUDITH D. ROEHM Ontonason County

07/19/95

APR 2 9 1996

10"

12"

Hemlock

Sugar

S86°E

N83°E

LAND CORNER RECORDATION CERTIFICATE

3/ 280 JEM Fee:

E۸	or corners in COMMISS	これが Filing F	Requireme	ent of Act 74, Mich. F	P.A. 1970		1 22 21 2	2 0:	4	
_	<u> ONTONAGON</u>	Located In:		Corner Code #						
	(County)				<b>\</b>					
1.	Public Land Survey	T48 F T F T F T F	l	(A-11) & M-11						
2.	Property Controlling in Section	S T F	3			v.				
3	Miscellaneous	S T F								
٠.	Property in Section	S F			Regis	ster of Deeds S	Stamp & F	ile Nui	mber	
	, roporty in coolien	· ·	· <del></del>		L					—
	Lot No, Re					A B C D	E F G	н і	J K	<u> </u>
	Section Corner co T48N R39W.	ommon to 830 & 3	31, T48N	I R38W & S25 & 36		3 4 7 8	1 1	10	11	12-
I, <u>Far1 W. Applekamp</u> , in a field survey on <u>July 18</u> , 19 <u>95</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:						5	2128	22	+-	24-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.						12 31 32	-33	34	35	36
A.	Description of original m	onument and access	ories and/	or subsequent restorati	on:			•		
	Original Corner of Surveyor, July 18			Curtis, U.S. Dep	outy	PEER GR	. //			
	ORIGINAL BEARING	TREES:			5	zare u	) (LOP	lek	duy	0

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

18 Links

No evidence of original corner or bearing trees were found. At the corner position there was a  $\frac{1}{2}$ " Iron Re-bar flush with the blacktop surface. There is a four way road intersection at the corner position. The  $\frac{1}{2}$ " Iron Pin was used for several surveys in the area. I accepted the  $\frac{1}{2}$ " Iron Pin as the corner location and remonumented the corner as described in "C" below.

28 Links (18.48 feet)

(11.48 feet)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:.

At the corner position I set a  $3\frac{1}{4}$ " stamped aluminum cap over the  $\frac{1}{2}$ " Re-bar and insulated the two metals with a plastic insert. Cap is 3" below top of blacktop. Cap is stamped to read: COUNTY REMONUMENTATION, S30, S31, APPLEKAMP of the stablished the following bearing trees:

APPLEKAMP of the stablished the following bearing trees:

APPLEKAMP of the stablished the following bearing trees: aluminum or insert. Cap is 3" below or insert. Cap is 3" professional or insert. Cap is 3" below or insert. Cap is 3" professional or insert. Cap is 3" professi and a witness monument.

6" Scotch Pine N35°W 54.00 feet -8" Maple N60°E 48.80 feet 4" Scotch Pine S41°E 70.26 feet

Date July 18, 1995 17610 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No.

REVISED MAY 14, 1975 REVISED JAN., 1983

KERKESEMTATIVE

7-18-95

COUNTY