JUDITH D. ROEHM Ontonason County LC 4/207 JEM 10/18/96 15:04

Fee: 9.00 Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ONTONAGON Located In: Corner Code # SURVEY REMONUMENTON T48NR 39W <u>I-6</u> 1. Public Land Survey MAY 2 2 1897 COMMISSION 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number _, Recorded Plat 4. Lot No. 5. Private Claims 1 Corner common to Sections 14 & 15, T48N R39W. 3 $\lfloor \text{Earl W. Applekamp} \rfloor$ in a field survey on $\underline{09-30}$, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: R 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 on this certificate. 1 12 A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Artemas Curtis, U.S. Deputy Surveyor, September 23, 1851. Set Wood Post. ORIGINAL BEARING TREES: Hemlock 18" 28.38 feet N41°W S16°E Y. Birch 12" 3.96 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No original evidence was found. Corner was re-established by single proportionate measurement between opposite section corners and in the center-line of a gravel road. (Larson Road) Research on file with the Ontonagon County Remonumentation Program Representative. COUNTY C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; At the corner position I set a 5/8" $\times 24$ " rebar with a $3\frac{1}{4}$ " stamped aluminum cap 6" below the surface of the gravel road. I established a reference monument, a $2\frac{1}{2}$ "X30" split base aluminum pipe with a $3\frac{1}{4}$ " cap stamped to read: County Remonumentation, T48N R39W, R.M., $\frac{1}{4}$, S14, S15, 1996, P.S. 17610. I also established three other reference objects. 40.63' - 4" Spruce N42°-08'-30"W 589°-35'-53"E 71.59' REF. MON. P. Pole S15"-44'-30"W N47°-07'-56"E 109.53' -4" Aspen Date October 8, 1996 17610 Surveyor's Michigan License No.