JUDITH D. ROEHM 07/17/97 Ontonason County LC 4/291 JDR Fee: 9:00 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in	riiiig Kequire	ement of Act 74, Mich. P.A.	1970	
ONTONAGON (County)	Located In: Corn	er Code #		
1. Public 7 and Survey	T <u>48NR_39W</u> TR TR	<u>I-8</u>	REMORNAN	
2 Branath Controlling			OCT a o	1997
2. Property Controlling S TR			COMMISSION	
Property in Sec.	S TR		Register of Deed	ds Stamp & File Number
4. Lot No, Recorde 5. Private Claims	d Plat		1 A B C D E	FGHIJKL
Quarter Corner commo	on to Sections 22 &	23, T48N R39W.	2 6 5	-4-3-2-1-
i, Earl W. Applekamp, requirements of P.A. 74, Michigan I conformance with regulations and rul United States Department of the Interthat the corner points mentioned in Board of Land Surveyors or by a recovered, found as expressed below	P.A. of 1970, the corner points me es therefore as required in the curr rior, Bureau of Land Management lines 3, 4 and 5 above were in cont Decree of a Court of Law; esta	intioned in lines 1 and 2 above were ent manual of survey instructions of t or by a decree of a Court of Law and formance with the rules of the Michig	the 5 17 17 18 17 18 17 18 18	-16 -15 -14 -13 - -21 -22 -23 -24 -
NOTE: Not more than 2 corner on this certificate.	s, all in the same town and rang	e, may be recorded	9 10 - 30 - 29 11 12 - 31 - 32	-28 -27 -26 -25 - -33 -34 -35 -36
A. Description of original monu	ment and accessories and/or	subsequent restoration:	13	
Original corner est Surveyor, September	ablished by Artemas 19, 1851. Set Wood	Curtis, U.S. Deputy 1 Post.		
ORIGINAL BEARING TR	EES:			
10" Fir N80° 6" Cedar S70°				
B. Description of corner evide	nce found and/or method app	lied in restoring or reestablishing	corner:	
a County blacktop r re-established by s	e was found. Corner coad running East & M ingle proportionate orners and in the ce	West. Corner was measure between		
Research on file wi Program Representat		unty Remonumentation	EEER GRO	Cup APPROVED
C. Description of monument to	or corner and accessories esta	blished to perpetuate locating th	COUNTE ne position of the corner:	7-15-97
At the corner positive below the top of black 2½"X30" aluminum processing Remonumentation, Talso established	tion I set a 5/8"X8" Lacktop. I establis tipe with a 3" cap s 18N R39W, R.M., \frac{1}{4}, S 3 other bearing tree	rebar with a stampe thed a reference monu- tamped to read: Cou 22, S23, 1997, P.S. es and reference obj	d cap 2" ment, a	EARL W. APPLEKAMP PROFESSIONAL SURVEYOR NO. 17610 APOFESSIONAL
5" Balsam S54	1°E 52.29' -	Power Pole S14°W Power Pole N17°W	104.12' E 82.40'	OFESSIONAL MINISTER
Signed by Lack W	applek any	Date	June 14, 1997	*
Surveyor's Michigan License N	// A			