APR 2 5 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

		Filing Requiren	nent of Act 74, Mich. P.A. 197	0
		Located In:	Corner Code =##	
<ol> <li>Public Lan</li> <li>Property C in Section</li> <li>Miscellane</li> </ol>	controlling S	T 48 R 42 T R T R T R T R R T R R		Recorded Octombor 5 1994  81 2:05 0'clock P. M. In  1994  Page 222  Register of Deeds Peeds  Register of Deeds File Number
Property in Sec.         S T R				
4. Lot No, Recorded Plat A B C D E F G H   J K L N  5. Private Claims				
Sections 3, 4, 9, & 10, T48N R42W  I. <u>Earl W. Applekamp</u> in a field survey on <u>November 05, 19 94</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 36	
A. Description of original monument and accessories and/or subsequent restoration:				
Corner established by Austin Burt, U.S. Deputy Surveyor, August 1848. Set Cedar Post.				
Original Bearing trees:				ONTONAGON COMMTY  PEER APPROVED
Elm 1	4" S55°E	91 Links (60	.06')	LW Spelskamp Out to Rep
Elm 1	o" N77°W	30 Links (19	.80')	Ont 6 Rep 11-30-94
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
In a survey in 1993 I found a $\frac{1}{2}$ " threaded iron rod set at the corner location. The location of this iron rod was in agreement with the calls to a creek to the West and South. The iron rod was tied to trees and cutting lines were evident. I accepted the location and set a more substantial 1" Drill Steel and tied to trees. In 1994 I remonumented the corner as shown below.				
Research on file with the County Remonumentation Program Representative.				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
E S t	pipe with a $3\frac{1}{4}$ " ostamped to read: $69 \text{ S10}$ . T48N R42V	cap over a 1" Dri County Remonume V, 1994, P.S. 176 aring trees and I N75°W 24.70'	24"x30" aluminum ' 111 Steel. Cap entation, S3, S4, 510. I established reference objects.  - Black Ash 12" N01°E - Steel Sign Post 0.80	EARL W. APPLEKAMP PROFESSIONAL SURVEYOR NO. 17610 OFESSIONAL APPLEKAMP APPLEKAMP SURVEYOR NO. 17610 OFESSIONAL APPLEKAMP APPLE
		4	·	TANDARD THE STORY OF THE STORY
Signed by	tail W	applekamp	Date	November 28, 1994
Surveyor's Michigan License No. 17610 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED JAN., 1983				