## REMONUMENTATION

JUDITH D. ROEHM Ontonason County LC

10/26/95

1

1 of

3/ 375 MEL 9.00 Page

APR 2 9 1996

3. Miscellaneous

Property in Section

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION		SION Filing Requ	Filing Requirement of Act 74, with. P.J	
	ONOTNAGON (County)	Located In:	Corner Code #	
1.	Public Land Survey	T 48 R 42 T 48 R 43	$\frac{A-2}{M-2}$	
2.	Property Controlling	T R T R S T R S T R		

Register of Deeds Stamp & File Number

\_ , Recorded Plat\_ 4. Lot No. Private Claims \_  $\frac{1}{4}$  Corner common to Section 1 & 6, T48N R42W & T48N R43W

I, <u>Ear1 W. Applekamp</u> in a field survey on <u>August 28</u>, , 19 <u>95</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by John Burt, U.S. Deputy Surveyor, August 13, 1848. Set Hemlock Post.

ORIGINAL BEARING TREES:

20" Black Oak \$71°E 9 Links 5.94 Feet 8" Hemlock N37°W 24 Links 15.84 Feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

At the corner position I found a squared wood stake set in a pile of rocks. Blazed lines went North and West from this position. The original notes called a ledge 5 chains South, which was in agreement. A top of the hill call 3.50 chains North was also in agreement. A miners home 3 chains East was not found.

I restored the corner at the stake and pile of rocks, as this location was consistent with the original calls. I set a monument and ties as described in "C" below.

Research on file with County Remonumentation

Program Representative.

polekan

COUNTY BEPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a  $2\frac{1}{2}$ "x30" aluminum pipe with a  $3\frac{1}{4}$ " cap stamped to read: COUNTY REMONUMENTATION, T48N R42W, R43W,  $\frac{1}{4}$ , S1, S6, 1995, P.S. 17610. I established the following bearing trees and reference objects:

lekoup

10" Oak N26°W 6" Maple S81°W

23.15 Feet 23.79 Feet

EARL W.
APPLEKAMP
PROFESSIONAL
SURVEYOR
NO.
17610 Steel sign post South, 2.30 Feet Survey.

6" White Birch S72°E 41.34 Feet No. 17610 POFESSIONAL AND ADDRESSIONAL AND ADDRESSI

Surveyor's Michigan License No.

Date September 01, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983