APR 2 9 1996

JUDITH D. ROEHM Ontonason County

10/26/95

10 3/365 MEL

9.00 Fee:

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Secretaria de la constanta de

₽ase

1 I of

	ONTONAGOI (Counity)	N Located In:	Corner Code #	
1.	Public Land Survey	T 48 R 42 T 49 R 42 T R	E=1 (E-13)	
2.	in Section	S T R S T R S T B		
3.	Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number

___, Recorded Plat_ 4. Lot No. 5. Private Claims _

Section Corner common to Sections 4 & 5, T48N R42W and Sections 32 and 33, T49N R42W.

October 10 Earl W. Applekamp, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Corner established by William A. Burt, U.S. Deputy Surveyor, August 1848. Set Cedar Post.

ORIGINAL BEARING TREES:

Maple 10" N21°E 48 links (31.68 feet) N12°W Sugar 10" 41 links (27.06 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. At the corner position I found a $\frac{1}{2}$ " I.P., 2" below the blacktop at the intersection of Michigan Highway M-64 and M-28. I personally know of this corner being at this position for 30 or more years. This corner position has been used for numerous surveys in the area and is identified in the MDOT Highway drawings. I accepted the corner position and set reference monuments as shown in "C" below. Research on file with the County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the softness.

EARL W.
APPLEKAMP
PROFESSIONAL
SURVEYOR
NO.

At the corner position I left the $\frac{1}{2}$ " Iron Pin in place and set two $2\frac{1}{2}$ "x30" aluminum pipe reference monuments with a $3\frac{1}{4}$ " cap stamped to read: T48-49N, R42W, S.4, S.5, S.32, S.33, R.M., 1995, P.S. 17610. Cap has the bearing and distance from the corner stamped on it. Reference monuments are set $\frac{1}{2}$ " below the ground surface.

APPLEKAMP
PROFESSIONAL
NO.
17610
POFESSIONAL
ROFESSIONAL
FOR STATEMENT OF THE PROFESSIONAL
ROFESSIONAL
ROFESSIONAL 17610 POFESSIONE Ref. Mon. S50°W 49.37 feet - Power Pole N20°W Ref. Mon. N50°E 50.64 feet - Power Pole S40°W Reference Monuments and $\frac{1}{2}$ " Iron Pipe on line 82.17 feet Ref. Mon.

applekang Signed by Last 17610 J Surveyor's Michigan License No.

_Date October 11, 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983