SURVEY & REMONUMENTATION

APR 2 9 1996

JUDITH D. ROEHM Ontonason County

3/285 JEM

10

07/19/95

Fee:

10:31 9.00

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Page

For corners in

Property in Sec.

Ontonagon Located In: Corner Code ## (County) T_50NR 42W E-13 1. Public Land Survey T 49NR 42W. R R Т R 2. Property Controlling T Т in Section S Т R Miscellaneous

Register of Deeds Stamp & File Number

_ , Recorded Plat . Lot No. 5. Private Claims __

Section Corner 32, 33, 4 & 5; T.49-50 N., R.42 W.

19 _95 I, Richard L. Drahn in a field survey on June 8 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration: Corner established by William A. Burt on August 18, 1847. Original bearing trees; --- Sugar 16" N.17 E., 16 links (10.56') --- Sugar 9" N.15 W., 30 links (19.80') --- Black Oak 20" S.79 E., 45 links (29.70') --- Sugar 10" S.34 W., 60 links (39.60') ---

Corner recovered by Donald D. Lappala, RLS 12585 on 8/26/65 from retracement measurement to natural features and corners west and south. He set a 2" X 5' iron pipe monument with a stamped brass cap and the following new bearing trees; --- 10" Sugar Maple N.43 W., 24.7' --- 10" Sugar Maple N.07 W., 17.4' --- 8" Elm N.35 E., 27.3' --- Corner recorded in Ontonagon County in USFS B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Liber, Page Z-9 on 6/3/68.

Act 74 research on file.

Recovered Lappalas damaged monument on the north edge of a power line clearing and his BT s as follows: --- 11" Sugar Maple N.40 W., 24.63' --- 11" Sugar Maple North, 17.40' --- 13" Elm stub N.40 E., 26.99" --- and 1984 bearing trees by R.L. Drahn and C.M. Story --- 14" Sugar Maple S.07 E., 59.93' ---14" Sugar Maple S.46 W., 67.67' ---.

Resource grade GPS Lat. 46-40.728 N 89-34.368 W Long.

PEER GROUP APPROVED KELAGSENTATIVE 7-18-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I replaced Mr. Lappalas monument with a 2½" X 30" aluminum monument with a 3½" stamped aluminum cap and the following reference objects: --- 6' Steel Sign Rail N.24 E., 1.54' --- 4" X 4" X 7' Wood Sign Post (1965) N.51 W. OF MICHIG 2.1' ---. Damaged 1965 monument now lays on ground at site.

Surveyor's Michigan License No. .

July 4, 1995

MANAGE LAND FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

RICHARD L, DRAHN LAND SURVEYOR 21564