LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		•										
Ontonagon	Located in:	Corner Code #										
(County)												
1. Public Land Survey	T <u>SIN</u> R_ T R_ T R_											
Property Controlling in Section Miscellaneous Property in Sec.	S TR_ S TR_ S TR_			Re	gist	er of	Deed	ls S 1	temp	& File	e Nu	nbe
4. Lot No, Reco	rded Plat			ر 1 ک	В	<u> </u>	E	F G	<u> Э</u>	<u>.</u> .	JΚ	L
				2	ļ 6	 	+	ļ	 ⊢∮.	+	· [—	_
		Oct 07 1996		3	H	\vdash	+	₩	┝╾┼		╬	\dashv
Stephan J. Szyszkoski	, in a field survey on	, 19 do hereby state that	t under	4	<u> </u>	⊢ •	+	<u> </u>	—1º0	┿	1,	—ıˈ;
		or points mentioned in lines 1 and 2 above to id in the current menual of survey instructions		5	\vdash	⊢⊢		╁╌┤	\vdash	+	+ +	-
United States Department of the	Interior, Bureau of Land Mi	lenegement or by a decree of a Court of Law: were in conformance with the rules of the Mi	and for	۰		3/2	+	. <mark>6—</mark>	<u> </u>	+	4	—i¦
	a Decree of a Court of	f Law; established, re-established, monum		<u>'</u>		+	+	H		+	+	7
recorded, round se supressed of				*	,,,,,	—20- 	T	ίĦ		\top	ίĦ	_;
NOTE: Not more than 2 con on this certificate.	iers, all in the same town	n and range, may be recorded		9 	<u>.</u>	—29-	;	28	27		26-	-25 -25
			:	11	\square	-	- -	╁┷┤			+	-
			;	12	<u> </u> -	32_	+	<u> </u>	<u></u> 3#	+	35-	⊢ 3€
				1			1	[i I	- 1		1

A. Description of original monument and accessories and/or subsequent restoration:
(K12) Quarter corner common to Sections 35-36. Corner reestablished in 1970 by A.O. Enger, RLS, at a position proportionate to the original record between Sections corners 1/2 mile north and south. The location of the position was determined by triangulation. 1970 mitnesses:-M. Spruce 9 MSM 19.3', + chiselled in rock face N12N 30.8', Henlock 6 N55E 14.0' (slope dist.). The corner position was marked by a 4" dia. aluminum cap embedded in concrete on a small rock protruding from the east face of Adventure Bluff. Enger notes the distance between section corners to be 5276.7'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

(Ri2) Found the 1970 monument, as described, in good condition, and at record bearing and distance from all three 1970 accessories. The Spruce is windthrown but the Hemlock is standing in good condition, with the 1970 blazes grown over. I surveyed to this corner, and to the adjacent section corners, from GPS control established near all three. I found this monument to be 0.5' Morth and 8.7' West of the proportionate position intended to be monumented in 1970. Considering the severity of the terrain, and the measuring technique used in 1970 to position the monument, I accepted the monument as a careful and faithful reestablishment of the position of the original corner. Left the monument in place and marked two new bearing trees as described below. Access to this corner is best from the Mortheast, along and up a faint trail and eventually through a short cave-like adit cut into the bluff, which also contains a narrow shaft apparently leading to workings below. The adit is nearly due north of the corner, and is quite close to it. The small rock ledge in which this monument is fixed is about 3-4' below and about 4' above ground upon which fairly good footing can be had. The overall distance between section corners north and south was found to be 5273.41'.

 C. Description of monument for corner and accessories established to perpetuals (K12) Found a 4 dia. aluminum MDRR 	e locating the position of the attent.
tablet concreted into a small rock	ALL OF THE STATE O
ledge. Blazed and scribed the	* STEPHAN J.
following new bearing trees:	* SZYSZKOSKI
6" R. Oak #85% 7.4" "1/45 MBT"	* LAND
10" N. Pine \$25N 10.4" "1/45 NBT"	SURVEYOR
The 1970 witnesses:	No.
8" Hemlock MSSE 14.0' (slope)	33986
+ cut in rock face N12N 30.8'	AND SUCK
Bearings are magnetic. Dist. Norizontal	
unless noted.	· · · · · · · · · · · · · · · · · · ·
Signed by Stephen I Smakely	Date <u>Sept. 17, 1997</u>
Surveyor's Michigan License No. 33986	