JUDITH D. ROEHM Ontonason County 10/23/96

4/ 221

16:24

9.00 Page

For corners in	rılıng Kequ	irement of Act 74, Mich. P.A	A. 1970
Ontonagon (County)	Located In:	Corner Code #	
Public Land Survey	т <u>51N</u> в 40М т <u>51N</u> в 41М	/ A-3 /	SURVEY & REMONUMENTATION
	T R T R		MAY 2 2 1997
Property Controlling in Section	S T R S T R		COMMISSION
Miscellaneous Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Ro	ecorded Plat		A B C D E F G H I J K L
			2
Joseph C. Domitrovich	in a field survey on	September 26 , 19 96	4 - 7 - 8 - 9 - 10 - 11 - 12 - 5
do hereby certify that under regin lines 1 and 2 above were in co	uirements of P.A. 74, Michigan lonformance with regulations and	P.A. of 1970, the corner points ment d rules therefore as required in the c tment of the Interior, Bureau of	tioned 6 18 17 16 15 14 13 -
Management or by a decree of 5 above were in conformance	a Court of Law and/or that the with the rules of the Michigan	corner points mentioned in lines 3, Board of Professional Surveyors or ented, re-monumented, recovered.	4 and 8 19 20 21 22 23 24 r by a
as expressed below:		,	10 - 30 - 29 - 28 - 27 - 26 - 25 -
NOTE: Not more than 4 cor on this certificate.	ners, all in the same town a	nd range, may be recorded	12 -31 - 32 - 33 - 34 - 35 - 36 -
A. Description of original i	monument and accessories	and/or subsequent restoration	7:
1 2) Corner Common to Co	rationa C 9 7 TEAN DAM	M C 4 0 40 TF4	AL (D.44)44

151N. R40W. and Sections 1 & 12, 151N. R41W

1845 - William A. Burt set post

S 530 W 16" Hemlock

16 links 19 links

10" Cedar N 450 W

1940 - T.H. Wilcox, in Supervisor's Plat of Government Lots 3 & 4, Section 6, T51N, R40W, shows the corner as a concrete monument and also shows concrete monument 33' to the East.

M.S.H.D., in M-64 Highway Plans, show corner as a 1 1/2" iron shaft and give angle and distance off centerline and two <u> 1969 - </u> witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner and accessories have been obliterated by road construction. I found a bent iron bar under pavement, which matched the angle and distance off centerline. I also found a square concrete monument 33.06' to the East as called for in plat.

I accepted the iron bar as the corner and placed a 5/8" x 24" rebar over it.

Research on file with County Remonumentation Representative.

10-16-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Corner is a 5/8" x 24" rebar with a 3" diameter aluminum cap stamped to read: S.1, S. 6, S. 12, S. 7; T.51N, R.40W;R.41W;1996; P.S. 37273; COUNTY REMONUMENTATION. Corner falls 5' East of centerline Townline Rd. I established a Reference Monument (R.M.) to the West, a 2" x 30" aluminum pipe with 3" diameter aluminum cap stamped to indicate the corner is 34.30" to the East.

Witnesses: **Aluminum NGS Monument** N 760 05' 50" E 25.90 S 390 W **NE Corner Church Steps** 76.65 N 89⁰ 54' 06" W R.M. 34,30" N 85° W **Power Pole** 33.92 N 50⁰ 03' 10"W Aluminum NGS Monument 46.52 N 720 E Power Pole 26.45

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

c. womita

Surveyor's Michigan License No.

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963

0 F M/C

JOSEPH

DOMITROVICH

LAND SURVEYOR

No. 37273

CAND