## LAND CORNER RECORDATION CERTIFICATE Ontonseon County

Filing Requirement of Act 74, Mich. P.A. 1970 of 1

Ontonagon County Remonumentation Corner Rec. Date 07/27/99

RECORDING FEE: 5 < 206 10lime 14:55 9.10

For comers in

**Ontonagon County** Located in: Corner Code # T51N R40W K . 7 1. Public Land Survey T T R T R T R 2. Property Controlling in Section Ş T R Miscellaneous 2 T R Property in Sec. S

SUBVEY & REMONUMENTATION

MAR 23 2000

SECTION

Register of Deeds Stamp & File Number

4 Lot No.

, Recorded Plat

5. Private Claims

PEER GROUP APPROVED

I, Joseph C. Domitrovich, in a field survey on July 12, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

5 6 7 A 9 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

## (K-7) Corner Common to Sections 13, 14, 23 and 24, T51N, R40W

1845 - William A. Burt set a lynn post; 8" sugar, S17°W, 23 links; 12" sugar, N34°E, 25 links.

1976 - Keith Sackett P.S. 19006 found a 36" rebar set by Billy Buckler, R.L.S. He placed a 1" pipe with a 4" MDNR cap at the corner and established 3 New Witnesses; 10" Ash, \$58°W, 30.8'; Fence corner, North, 22"; 7" Ash, N82°W, 46.9' (Corner Recorded in Liber 1, p. 51 of Corner Records).

1992 - Steve Szyszkoski, P.S. 33986 recovered Sackett's Witnesses but the monument was gone. He re-established a 1" pipe with a 4" MDNR cap at record bearings and distances from Sackett's witnesses. He added three new witness trees: 5" Basswood, N24°E, 24.6'; 3" Red Pine, S62°E, 30.2'; 5" basswood, S58°W, 37.3'.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original comer or accessories. The area around the corner has been clearcut and an east-west logging road runs over the corner position. I found no remains of the monument placed by Steve Szyszkoski, but I recovered his bearing trees and Sackett's 7" Ash to the NW, I re-established the corner position at record bearings and distances from the measuring notch of the recovered DNR bearing trees. This position works well with GLO distances and distances from Steve Szyszkoski's Plat of survey.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" rebar with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION, T51N; R40W; S.13, S.14, S. 23, S. 24, 1999; P.S. 37273. Carner falls in middle of lagging road on extension of fence to the North. Ties:

5" Red Pine	S60°E	30.47' (DNR bearing tree; added nail to side)
Steel Survey Sign Post	South	34.79' (To Face)
Steel Sign Post (No Trespassing Sign)	\$18°W	11.11' (To Center)
6" Basswood	\$59°W	37.57' (DNR bearing tree; added nail to side)
8" Twin Ash	N81°W	47.27' (DNR bearing tree; added nail to side)
Steel Sign Post (No Trespassing Sign)	N06°E	8.12' (To Center)
N1/4 Corner Section 23	S89°52'03"W	2651.84' (2652.14' Szyszkoski)
NE Corner Section 14	N00°24'35"W	5243.61'
SE Corner Section 23	800°10'05"E	5243.61' (5246.74' Szyszkoski)

NOTE: Bearings to witness objects are magnetic. Distances are to a nall in side of the witness object unless noted,

Signed by

7/20/99 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSI

JOSEPH DOMITROVICE LAND SURVEYOR

Surveyor's Michigan License No. 37273