SURVEY &

APR 2 5 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

OC INTROCES	Filing Requir	rement of Act 74, Mich. P.A.	1970
For corners in Ontonagon		1	
(County)	_ Located In:	Corner Code ##	
	#4U _ MAL	VA	Recorded Decamber 19 94
Public Land Survey	T <u>51N</u> R <u>40M</u> TR	_K8	at 30 o'clock P. M. III
	T R		Liber Survey 3 page 244
	T R		Register of Doeds
2. Property Controlling	S R		Hogania a
in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S R	L	
4. Lot No Re	corded Plat		- ABCDEFGHIJKŁ
5. Private Claims			
			3 1 3 3 2 3 1 3 3 3 3 3 3 3 3 3 3 3 3 3
			4 7 8 8 10 11 12
ı Stenhan J. Savsakoski	in a field survey on ANG	ust 29 <u>, 1994</u> , 19	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			ed allililili
in lines 1 and 2 above were in	conformance with regulations a stions of the United States Depa	ind rules therefore as required in th irtment of the Interior, Bureau of Lar	ne 7
Management or by a decree of a	Court of Law and/or that the corn	er points mentioned in lines 3, 4 and	15 8 19 20 21 22 23 24
above were in conformance with	the rules of the Michigan Board	of Land Surveyors or by a Decree of -monumented, recovered, found a	fa 9
expressed below:	restablished, monamentos, to	monement, reserves, reserve	10 30 29 28 27 26 25
NOTE: Not more than 4 co	rners, all in the same town a	and range, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
A Description of administration		nd/or subsequent restoration:	13
D. Description of recovery	idence found and/or mathod	ennlied in restoring or reastable	liching corner
		applied in restoring or reestabl	
Recovered the monument place monument placed in 1977 is have been relied upon since monumented section corners,	ed in 1977, as described, and 10.6' east and 6.8' north of 1977. I rejected it as monun	d at record bearing and distance the postion proportionate to the menting the 1/4 corner. Reestat to Act 74, P.A. 1970, and bein	position of the original corner on the ground. If from the 1977 accessories. Determined that the original record, and, as it appears not to plished the corner on a straight line between ag 2623.37' north and 2623.37' south. The 1977
C. Description of monumer Placed a 3/4" dia.x48" long capped with a 3 1/4" dia al stamped: "County Remonument R40W 1/4 23\24, 8-29-94, PS which bear the following: 10" Maple N51E 11.7" mrkd "6" Sugar S75W 24.9' do 10" Maple N25W 10.7' do 5" Ash S20E 45.8' do metal sign post S85W 1.0' Distances are to notch in 1	aluminum rod uminum cap ation T51M 33986" from 1/4S MBT"	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	ontonagon county PEER APPROVED Lack W applehaus Ont. la Rep. 12-15-94-
Bearings are magnetic.	tope I & so	1 1.	0-5-1994
Signed by	Jum J. Nagy	Date	
Surveyor's Michigan License		nt of Natural Resources - Fores	ORM APPROVED BY MICHIBAN STATE BOARD OF LAND SURVEYORS, JAN. 28, t. Management. Division. Revised May 14.
	tot one arourant nebatome	THE ME CONTRACT HOSCALODS 19105	MEVISED JAN., 1