LAND CORNER RECORDATION CERTIFICA Filing Requirement of Act 74, Mich. P.A. 197	D 3.00
For corners in	
ONTONAGON Located In: Corner Code #	
1. Public Land Survey T51N R 41W A-6 M-6)	REMOVEMENT ON
TR	JAN 1 1 1999
2. Property Controlling S TR	SECTION
3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
5. Private Claims	2 6 5 4 3 2 - 1 -
Corner common to Sections 13 & 18, T51N R41W & T51N R42W. [Earl W. Applekamp , in a field survey on March 26, 1998 do hereby state that under	3 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,	7
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	10 30 29 28 27 26 25
	11 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
Original corner established by Austin Burt, U.S. Deputy Surveyor September 1845. Set Wood Post.	or,
ORIGINAL BEARING TREES:	
8" Fir S70°E 2.97 feet 16" Sugar N15°W 23.76 feet	·
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn	ner;
No original evidence was found. Corner falls in the paved are Michigan Highway M-64. Corner was re-established by single prionate measure and on line between opposite section corners No & South.	a of opor-
Research on file with the Ontonagon County Remonumentation	PROFESSIONAL &
Program Representative.	NO. 17610 17610 OFESSIONAL TRANSPORTED OF THE PROPERTY OF THE
5-13-98 COUNT BERREY	sition of the corner:
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner position I set a R.R. Spike in the Northbound landshapped in the Northbound landshapped in the corner is 10.8 feet East of the Highway cert is 10.8 feet East of the Highway cert is established two reference monuments and two bearing objects monuments are 2½"X30" split base aluminum pipe with a 3" cap see County Remonumentation, T51N, R41W, R42W, ¼, R.M., S13, S18, S18, S18, S18, S18, S18, S18, S18	ane of Michigan ater-line. Reference stamped to read:
REF. MON. N67°-22'-42"W 61.66' - Nail in 6" Ash S81°-16 REF. MON. N85°-15'-54"E 94.82' - Center-line M-64 Due Wo)'-47"W 60.25' est 10.8'
Signed by Lail W applekaup Date Mary	ch 27, 1998
Surveyor's Michigan License No. 17610	