LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in Ontonagon	Located In:	Corner Code ≠
_	(County)		*
1.	Public Land Survey	T 52H A 37H	<u>M7</u>
	· · · · · · · · · · · · · · · · · · ·	T 52N R 37N	#6
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	

Register of Deeds Stamp & File Number

4	LALNA	Recorded Plat

Property in Sec.

E Bullinda Otaliana	5. Private Claims			
		Outrode Oterane		

H6	October	12.	1995

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M7) Corner common to Sections 18-19 T52H-R36M and Sections 13-24 T52H-R37M. Corner established in 1845 by Wm. A. Burt. "80.00 Corner of Sections 13824 and set post. Sugar 10 S39M 61, do 12 N37M 28". Corner noted in Head records as 1 1/2" iron pipe found January 24, 1966 with the following witnesses: 7" Elm (C&H tag) 7" Hard Maple (Yellow tag). Found no subsequent record.

(M6) Quarter corner common to Section 18 T52N-R36M and Section 13 T52N-R37M. Established in 1845 by Wm A. Burt: "40.00 Set or Section post. Hemlock 12 S27M 37, do 16 M30M 28". Mead records dated Jan 24, 1966 state: 4" Ash post at corner Old Hemlock stump (B.T.) M26M 17 ft., 8" Hard Maple (Beaver) S24M 9 ft". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M7) Original post and accessories not recovered. Recovered a 1 1/2" iron pipe with 8" Sugar Maple and yellow Yulcan tag facing. The 7" elm with C&H tag noted in 1966 is dead and has recently fallen. Distance north 1/2 mile to probable original 1/4 corner and 1 mile to original section corner check reasonably well with the original record. I accepted the pipe as the best available evidence of the position of the original corner. Left the pipe in place and marked 4 mitnesses as described below.

(M6) Original post not recovered. Mead's Ash post was not recovered. Resonumented the corner at record bearing and distance from the remains of the original bearing trees. The Hemlock NN was recovered as a rotted stump of proper size and species. No markings were found. A distinct stump hole marks the location of the other Hemlock BT. The corner is also in accord with Mead's 8" Maple, recovered as described. Also, An old unreadable location poster, possibly by Copper Range, faces the corner on a 14" Sugar. A dead 4" squared Sugar was found adjacent. Distances North and South to adjacent Section corners are -0.06 ch. and +0.32 ch. respectively, compared to the original record. At the position for the corner, I placed a 1"I.0.x36" iron pipe capped with a 4" dia. cast aluminum MOMR tablet, appropriately stamped.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M7) Found I 1/2 iron pipe.	(M6) Set 1 pipe with 4 munk cap.
Blazed and scribed the following new	Blazed and scribed the following new
bearing trees:	bearing trees:
9" Sugar found with Vulcan tag	14" Sugar NOBW 26.6' "1/45 MBT"
S18W 7.0' "S24 NBT"	15" Maple N47E 10.1' "1/45 N8T"
5" Sugar S48E 21.1' "\$19 MBT"	10" Sugar S20E 3.7' "1/4S MBT"
10" Sugar N42E 20.9' "518 NBT"	8" Sugar NBON 17.6' "1/4S NBT"
12" Sugar H18H 26.4" "S13 HBT"	Bearings are magnetic. Placed a 3"
Bearings are magnetic.	squared ash post adjacent.

STEPHAN J.
SZYSZKOSKI
LAND
SURVEYOR
No.
33986

Signed by Stephen J. Songspoli

10-26-95

Surveyor's Michigan License No. _

33*986*

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
TAST MAGGINERANT (DAVISION) REVISED MAY 14, 1975