SURVEY &	
JEMONIMENTATION	

DEC 1 6 1996

COMMISSION

JUDITH D. ROEHM Ontonason County 4/ 128

07/12/96 15:04

Fee:

9.00 Page

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		0	
Ontonagon (County)	Located In:	Corner Code #	
Public Land Survey	т <u>52N</u> R <u>40W</u> т R т R		
Property Controlling in Section Miscellaneous Property in Section	T R S T R S T R S T R		Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H J K L M 2
do hereby certify that under red in lines 1 and 2 above were in a manual of survey instruction Management or by a decree of 5 above were in conformance	quirements of P.A. 74, Michigan F conformance with regulations and s of the United States Depart f a Court of Law and/or that the with the rules of the Michigan	June 18 , 19 96 P.A. of 1970, the corner points mentions i rules therefore as required in the curre tment of the Interior, Bureau of Lar corner points mentioned in lines 3, 4 ar Board of Professional Surveyors or by ented, re-monumented, recovered, four	ed 6 18 17 16 15 14 13 nd nd 7 1
NOTE: Not more than 4 co on this certificate.	rners, all in the same town ar	nd range, may be recorded	12 31 32 33 34 35 36 13

Description of original monument and accessories and/or subsequent restoration:

(I-12) 1/4 Corner common to Sections 34 & 35, T52N, R40W

1845 - William A. Burt set post

12" Hemlock

N 540 E

24 links

18" White Pine

N 370 W

25 links

1922 - E.J. Donnelly C.E. replace corner with an iron bolt from the original White Pine bearing tree. This corner subsequently noted in Supervisor Carroll's Plat of Gov't lots 3 & 4 of this section, in 1928.

Michigan State Highway Department found a 1/2" iron pipe and gave 3 witnesses and also angle and distance off of centerline control. Numerous private surveys note the same corner as found by the Highway Department.

1988 - Robert Mick P.S. 16936 in survey recorded in Liber 1 page 97 of Surveys shows comer and distance east to center 1/4 corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 5/8" O.D. iron pipe which matched angle and distance well off of centerline control highway M-64. Pipe also worked well with one remaining witness object, and works well with other corners in area as well as with Mick survey.

This pipe has been the long accepted 1/4 corner and I have monumented it as such.

Research on file with County Remonumentation Representative.

07-08-96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 24" rebar with a 3" diameter brass cap stamped to read: 1/4 S.34, S.35; T.52N., R.40W.; 1996; P.S. 37273. Corner falls 5.7' north of centerline Johnson Road and 2.5' west of centerline Noble Road. Also established a reference monument which is a 2" x 30" aluminum pipe with 3" diameter aluminum cap stamped to indicate the 1/4 corner is 24.42' east.

١Mi	tna	sses:
	uio.	3393.

N 680 W 14" White Birch 31.60 N 33° E 14" Red Pine 60.65 Power Pole #10

40.13' (existing nail and tag) S 370 W

Anchor Pole

S 45° E

37.60

Reference Monument West

Surveyor's Michigan License No.

24.42

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

REVISED MAY 14.

DOMITROVICH

LAND SURVEYOR