MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 33 NR 4 E

		Pr	esque_Is	те	COUNTY
DESCRIPTION OF CORNE	R 1/4 corner	common 1	to Secti	ons 10) and 15
DESCRIPTION OF CORNE	R MONUMENT	Im pipe	witn_4"_	præss	cap
WITNESSES TO CORNER		. -		· -	
	• W. Pine	6# -	STSE		23.7 feet
	+ Cedar 7		n56w		61.9 feet

* G.F.DeLaMater NBTs

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Land Surveyof while making a survey of Section 15. Found ½" iron bar in place as restored by G.F.DelaMater in 1944. Stumps of both government Tamarack BTs in place, the NW showing evidence of notch of lower face. Very old post bottom in place here also. A 1" pipe by unknown is S62E about 65 links. This point does not conform too well for midpoint or line on this mile, but the evidence appears to outweigh the erroneous measurements.

Corner was placed and witnesses noted May 5, 1960.

SURVEYORS SEAL

SIGNED LEWILL SURVEYOR DATE 5/6/60_