93 DEC 20 PH 4: 49

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

REVISEO MAY 14, 1 REVISED JAN., 1

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

inct M. Jams For corners in REGISTER OF DEEDS PRESQUE ISLE Located In: Corner Code ## D-3 T 34N R 2E Public Land Survey ___ R ___ T ____ R _ LIBER 307 PAGE 900 _ T _____ R ___ 2. Property Controlling S ____ T ___ R ____ in Section __ T ____ R ____ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ T __ __ , Recorded Plat ___ 4. Lot No. _ 5. Private Claims ... September 3 Ronald R. Bischer in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: S53°E July 1855 25.62 18" Maple 30" Twin Elm N50°E Geo. H. Cannon set Wood Post 29.88 15" Beech S70°E 38 links S26°E 49.90' Top of Fire Hydrant Recorded on Page 26, Land 18" Sugar N70°W 17 links AND STATE OF MICHIO 1973 - Delmar E. Porter Recordation, October 12, 1973. Found 3/4" Pipe, raised w/2" Rod and Cap #15410 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: BISCHER LAND SURVEYOR NO. Found 3/4" Pipe in Monument Box. 22428 S58°E 25.62' 20" Maple STRED LAND ST PED LAND STATE 49.90 Top of Fire Hydrant CHEMEN & PERCRUMENTATION Raised 3/4" Pipe with $\frac{1}{2}$ " Rod and Cap #22428. 1993 COMMISSION C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: D-3½" Rod and Cap #22428 in 3/4" Pipe inside Monument Box S58°E 20" Maple 25.621 Ratified by Peer Group S28°E 49.90 Top of Fire Hydrant in accordance with P.A. 345 N59°W 36.31' NE Corner of Block Wall S31° W 72.81' SE Corner of Block Wall Chairman / Date _ *Witness tag and nail used on 20" Maple. Signed by Ronald R. B. Date 12-13-93 Surveyor's Michigan License No. 22428

<u>Notes</u>

Range 2E Section 5, 8 , 34N D-3 Corner, Township

<u>Activity</u>

1855 Resurvey Geo. H. Cannon

1973 Delmar E. Porter #15410

1993 Remonumentation Ronald R. Bischer #22428

Monument & Accessories

Set Wood Post 15" Beech S70°E 38 links 18" Sugar N70°W 17 links

Found 3/4" pipe Three witnesses

Recorded on Page 26, Land Recordation, October 12, 1973

Found 3/4" pipe in Monument Box, raised w/2" rod & cap #22428 S58°E 25.62' 20" Maple found nail w/tag #22428

S28°E 49.90' Top of Fire Hydrant
N59°W 36.31' NE corner of Block wall (new witness)
S31°W 72.81' SE corner of Block wall (new witness)