## 1995 PRESQUE ISLE COUNTY, STATE OF MICHIGAN REMONUMENTATION

Ç,	D	I	4	
----	---	---	---	--

## COMMISSICATION Requirement of Act 74, Mich. P.A. 1970 PRESQUE ISLE COUNTY RECORDED

LIBER 316PAGE 297

For	corners	: in
101	COLLEGA	

	Presque Iste	Located In:	Corner Code =##
Ť.	Public Land Survey	136N R2E	L-1
		T R	
		T R	
		T B	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Don't Live	0 7 0	

95 OCT 20 PH 4: 29

net M. Samb

Register of Deeds Stamp & File Number

\_\_\_ , Recorded Plat \_\_\_

5. Private Claims

I, Norman J. Quaine in a field survey on February 17 \_\_ , 19 \_95 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-1

GLO Notes

Resurvey 1856

Tamarack 6" N50°E 24 Tamarack 9" N20°W 10

George H. Cannon

Made reference to in the Plat of "Bella Vista" of T37N,R2E, Sec. 36,Dated 8/24/72, by R.S. Scott

As recorded in Presque Isle Co. Register of Deeds

Dec 1975

Delmer E. Porter #15410

LCRC Page 98

Fd 1" Ax1e w/ o1d 3"x3" Ceda: stake & newer 3"x3" cedar stl

Left Same

North 9.41' 7" Cedar S50°W 11.04' 6" Cedar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

February 17, 1995

Presque Isle County State Remonumentation

Norman J. Quaine #33984

Fd. 1" Axle by cedar post

S88°W 4.24' 6" Balsam Stump S50°W 11.04' 6" Cedar in poor condition N23°E 9.25' 7" Cedar

Porter's Survey P.C.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Left 1" Axle by cedar post

N23°E 9.25' 7" Cedar

S71°E 10.48' 6" Cedar

S12°W 12.20' 9" cedar

N16°W 16.54' 5" Cedar

Ratified by Peer Group in accordance with P.A. 3

Chairman De

Date \_

\*Witness tags & nails used,

Signed by

Surveyor's Michigan License No.

OCTOBER