## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T. 24 - NR - 4 - # -

			Rescouner COUNT
DESCRIPTION	OF	CORNER	Section -Corner common to -Sections-19,20,29,30
DESCRIPTION	OF	CORNER	MONUMENT_im Pipe with in Brass cap
WIT TNESSES	то	CORNER	-84 -Oedar = 8 65-E = 28 Links
			-10# GedarN-31 W = 54-Links
<i>)</i>			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.'s still in place, one in expellent condition.

Corner was placed and witnessed February 7, 1952.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/15/52 --