Sagina (County	Located In: Corner Code #	LIE	8' (MIL RES SAG 144	LBHED PISTER PROVIDE PAGE 1	14.00 00-00 100-00 147		
Prop	rerty in Sec. S 1 1 1	1 A	ВС	D	E F G	9 H (JK	L
	-te Claima	2	6	5	4	3	2	1
0. 1 1111		3 - 4	7	8	9	10	11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			18	17	16	15	14	13
			19	20	21	22	23	24
			30	29	28	27	26	25
NOTE:	Certificate.	12	31	32	33	34	35	36
A. <u>F-11</u>	Description of original monument and accessories and/or subsequent rest 1/4 Corner, Sections 28, & 33, Chapin Township 1831 GLO wood post placed by Robinson Thomas, D.S. set a split distance o N46W 24lks (15.84') 14" Beech S40E 47lks 31.02') 6" Beech No subsequent record of restoration or perpetuation	of 40) chai	ns (264 - :::::::::::::::::::::::::::::::::::	R v 9	2006 3 N I	Y	
В.	Description of corner evidence found and/or method applied in restoring of	or re	esta	blishir	ig cor	rer:		
<u>F-11</u>	1/4 Corner, Sections 28, & 33, Chapin Township							
	Found no evidence of the original government accessaries. Found 1" iron bar in the a fence/tree line occupation to the North. Found no existing witnesses or conflicting Measured West to the found closing corner at D-11 3456.59' (GLO = 3445.20'), in 2640'). The prorated distance to E-11 calculates to be 2648.73' (GLO = 2640'). The from a split of the re-established E-11 and G-11 and falls 0.44' North of a line be that the 1" iron bar be accepted as the best available evidence of the position of replaced with a standard Saginaw County 5/8" re-rod with brass cap in a monuncero.	ng e nea ne p etwe f the	viden sured ositio en E- e origi	ce in th I East t n of the 11 and inal go	ie vicini to G-11 found I G-11.	ity of th 2656.0 1" iron We re	is positi 08' (GL bar is 3 ecommi	on. O = .68' end
C.	Description of monument for corner and accessories established to perpetu	ıate	loca	ting th	e posit	ion of	the cor	ner:
<u>F-11</u>	1/4 Corner, Sections 28, & 33, Chapin Township Set 5/8" re-rod with standard Saginaw County brass cap stamped "F-11 1999 39096" and monument box							

Signed by Surveyor's Michigan License No. 39096

S16W 164.17' Set PK/tag #39096 in E fc PP

S77E 39.84' Set ½" re-rod/flag on NE side of top of bank N68W 32.37' Set ½" re-rod/flag on NW side of top of bank N02W 25.03' Fnd 2" angle iron fence post N of Kramer Road

_ Date _

RM APPROVED BY MICHIGAN STATE TO ROUT TO THE PROPERTY OF THE P

DAPTED FOR WORD PROCESSING MARCH, 19