RECORDED/FILED

2	PROVED BY PEER GROUP 1999 REMONUMENTATION PROGRAM P.A. 345 OF 1990 SAGINAW COUNTY Filing Requirement of Act 74, Mich. P.A. 197			MII na	ED M	A & DODAN DEED NOTY.	,		
Sagin (Count	y) Chapin Twp.					1435			
1. Public Land Survey Telegraph									
Proj	perty in Sec. S T R	, A	В	C D	E F (S H E	JK	٤ ٤	
4. Lot 5. Priv	No, Recorded Platate Claims	2 3	6	5	4	3	2	1	
ı.	John H. Rauser , P.S. , in a field survey on September 17 19 99 .	4	7	8	9	10	11	12	
in lines	by certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 1 and 2 above were in conformance with regulations and rules therefore as required in the manual of survey instructions of the United States Department of the Interior, Bureau of Land	5	18	17	16	15	14	13	
Manager above w	ment or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 vere in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a f Law; established, re-established, monumented, re-monumented, recovered, found as	8	19	20	21	22	23	24	
expresse	ed below:	10	30	29	28	27	26	25	
NOTE:	Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	12	31	32	33	34	3 5	36	
A.	Description of original monument and accessories and/or subsequent res	itor	ation:						
<u>L-11</u>	1/4 Corner, Sections 25 & 36, Chapin Township 1831 GLO wood post placed by Robinson Thomas, D.S. 1972 Act 132 Certified Survey by Oliver M. Elliot, RLS #2097 as recorded on Road Commision Witness Cards	n L.1369, P.470 WAR = 9 2000							
					SECT	HON			
₿,	Description of corner evidence found and/or method applied in restoring	or r	eestal	blishin	g corn	er:			
<u>L-11</u>	1/4 Corner, Sections 25 & 36, Chapin Township								
	Found no evidence of the original government accessaries. Found 3/4" square iron bar, no monument box, 1'+ North of the centerline of asphalt. Found and checked two witnesses from 1977. Found the 2" iron pipe to the south, 34.68'. The distance is not shown on his survey, but due to a deep road ditch on the south side of road, the pipe may not have been set at 33'. Found bar falls in line with the westerly edge of drain to South, no occupation North. Spoke with the land owner to the North, he stated that he owned on both sides of the 1/4 line, which explains the lack of occupation North. Measured West to K-11 = 2614.13', measured East to the re-established M -11 = 2615.86'. Found bar falls 1.92' South of a line between K-11 and M-11. We recommend that the found 3/4" square bar be accepted as the best available evidence of the position of the original government corner and be replaced with a standard Saginaw County 5/8" re-rod with brass cap in a monument box.								
C.	Description of monument for corner and accessories established to perpetu	ıate	locati	ing the	positi	on of tl	ne cori	ner:	
<u>L-11</u>	1/4 Corner, Sections 25 & 36, Chapin Township Set 5/8" re-rod with standard Saginaw County brass cap stamped "L-11 39096" N73E 75.88' Fnd N&T S fc PP South 34.68' Fnd 2" pipe N73E 62.19' Set spike/tag #39096 in NW fc 18" Poplar S46W 73.41' Fnd N&T NW fc PP	" an	d mon			OMN HALSER	ilo is		
Signed by Date Date Date Surveyor's Michigan License No. 39096									
ourvey(FORM APP	ROVE	BY MICHI	GAN STAT	TED FOR V	E S\$10k	JAY JEED JA SSING MAR	. 28, 1971 114, 1975 AN., 1983 CH, 1993	