SAGINAW COUNTY RE-MON 1997 LAND CORNER RECORDATION CERTIFICATE RECORDED & FILED Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Taymouth Township	
Saginaw Located In: Corner Code #	Sep 25 9 23 PM '97
1. Public Land Survey T 10N R 5E L-13 T R T R T R	MILDRED M. DODAK REGISTER OF DEEDS SAGINAW COUNTY HIGH. LIBER 2027 PAGE 83
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Siber 7 Page 123 Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat	
	1 B C D E F G H I J K I 2 6 5 4 3 2 3
I, Ronald C. Prevost , in a field survey on 5-6 , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	4 7 8 9 10 11 1 5 6 18 17 16 15 14 17 7 8 19 20 21 22 22 22 2
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10-30-29-28-27-26-25 11
Description of original monument and accessories and/or subsequent restoration:	12 -31 - 32 - 33 - 34 - 35 - 36
L-13 Post set by J. Wampler about 1822. Maple 16 in S.45E. 15 L Beech 13 in N.30W. 2 1/2 L L.C.R.C. L4 P37, D. Rowe 1977,t-iron set. L.C.R.C. L4 P214, J. Martin 1979 1" iron bar set. Spicer notes of 1972, observed fence to N. at 2651' W of M-13. Spicer notes of 1974, dug at 2651' W. of M-13 found nothing, set 1" iron bar on line between K-13 & (L-1 T.9 NR.5 E.) and 66.00' West of said L-1 T.9 NR.5 E., measured East 2650.82 to M-13, previously 2651'	SURVEY & REMONUMENTATION MAR 1 8 1998
B. Description of corner evidence found and/or method applied in restoring or reestablishing c	SECTION
L-13 Found 1" iron bar L4 P214. Dug hole mid-way between K-13 & M-13 found t-iron 1.0' below gravel surface. Apparently Power iron 1.4 P27.	APPROVED BY PEER GROUP P.A. 345 OF 1990 SAGINAW COUNTY B-28-97
C. Description of monument for corner and accessories established to perpetuate locating the p	Osition of the corner
L-13 Replaced 1" iron bar with 5/8" re-rod, Sag. Co. re-mon cap & mon box 9-17-97. N.70°W. 69.57 nail & cap NE. side 30" Oak. North 30.52 nail & cap E. side 16" Elm. S.70°E. 68.45 nail & cap N. side 36" Oak. N.70°E. 86.59 nail & cap S. side 12" Apple. East 66.08 1/2" iron bar L-1 (T.9 NR.5 E.)	RONALD C. PREVOST PROFESSIONAL SURVEYOR 6
Signed by Ronald C. Prevost Date	9-25-97
Surveyor's Michigan License No. <u>24612</u>	