LIBER 1989 PAGE 2289 Liber 7 Page APPROVED BY PEER GROUP P.A. 345 OF 1990 SAGINAW COUNTY SAGINAW COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in THOMAS TWP REGISTER Corner Code # Saginaw ocated in: Thomas Twp. (County) IER OF DEEDS TER OF DEEDS TOUNTY MICH 1. Public Land Survey T12N R 3E T12N R 3E 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims 2 3 in a field survey on October 16, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 7 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: В NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 11 12 Description of original monument and accessories and/or subsequent restoration: <u>C-8</u> Set post at 40.00 chains North of C-7; 1822, Joseph Wampler 9" Maple-South, 7 links 14" Maple-N13°E, 13 links Set post at 40.00 chains North of C-9; 1822, Joseph Wampler 21" Pine-N33°W, 27 links 9" Beech-S12°E, 7 links L.C.R.C.-Martin (L1, P257) 1972; 3/4" pipe L.C.R.C.-Soltis (L2, P45) 1972; 3/4" pipe Surveys- (L1378, P411-L1352, P415-L1400, P276-L1666, P184) No L.C.R.C. or Surveys of record. From Spicer field notes, Nov. 1959, "Drove 2" by 48" pipe in remains of old fence corner with 18" left out of ground- wire fence all call for a 3/4" pipe. Survey-Wade-Trim (L1954, P1114) corner not identified. remains to South, East and West. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  $\frac{c-6}{c-8}$ Found 3/4" pipe over 5/8" rod over 3/4" pipe. No witness of record but distances between SW cor and Ctr 1/4 fit L.C.R.C. (L1, P257) & (L2, P45) well with unrecorded data provided by Spicer Engineering Co. & NE 107.74' (107.54' m) to SW cor. frame house Survey (L1666, P184) ENE 107.70' (107.54' m) to SW cor. frame house previous surveys by Ledy. SW 52.29' (52.20' m) to top ctr hyd. NW 41.80' (42.0' m, leaning) to Road sign post Monument accepted as best evidence of original position. Monument accepted as best evidence of original position. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  $\frac{C-8}{C-8}$ Set 5/8" rod with remon. cap inside 2" pipe. Set 5/8" rod with remon, cap in monument box. SW 94.37' to Nail in West side Power Pole 42.05' to nail & tag in W side light pole NW 106.20' to Nail in West side Power Pole 107.54' to SW corner house foundation NNW 95.81' to Nail in West side Power Pole ESE 84.60' to nail & tag in NE side 8" Oak 72.15' to Nail in 4" Oak SW 51.18' to top center fire hydrant

DUANE F. S. 21575 POFESSIONAL PONAL GUART **PROFESSIONAL** Date Signed by Date SURVEYOR No. 21575
POFESSIONAL PROFESSIONAL SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No. REMOS

MAY 1 6 1937

MAN SI

REVISED MAY 14,1975