APPROVED BY PEER GROUP P.A. 345 OF 1990	9 PAGE 2289	Liber	7	P	rge 1
SAGINAW COUNTY RILAND CORNER RECOINTY RILAND CORNER RECOINTY Filling Requirement of	RDATION CERTIFICA	NTE .			
For corners in Saginaw Located In: Thomas Twp.		SAGIN	RECO	Oct 3	स्र
1. Public Land Survey T12N R 3E T12N R 3E C-8 T R	<u>v</u>	YM COOMI	DRED M. D STER OF C	2	RECORDED & FILED
T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	·	Register of	Deeds St	amp & F	. •
4. Lot No, Recorded Plat 5. Private Claims		A B C D 1	E F (H I	J K L
I, <u>Duane F. Ledy</u> , in a field survey on <u>October 16</u> , 19 <u>96</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lir conformance with regulations and rules therefore as required in the current manual of United States Department of the Interior, Bureau of Land Management or by a decretate the corner points mentioned in lines 3, 4 and 5 above were in conformance with Board of Land Surveyors or by a Decree of a Court of Law; established, re-crecovered, found as expressed below:	nes 1 and 2 above were in of survey instructions of the ee of a Court of Law and /or h the rules of the Michigan	3 4 7 8 6 19 19 20	9 ——16 ——21		111 141 232
NOTE: Not more than 2 comers, all in the same town and range, may be re on this certificate.	ecorded	9 29 29 11 2 31 32	28	34	
A. Description of original monument and accessories and/or subsequent	t restoration:	131			
Set post at 40.00 chains North of C-7; 1822, Joseph Wampler 9" Maple-South, 7 links 14" Maple-N13°E, 13 links No L.C.R.C. or Surveys of record.	C-8 Set post at 40.00 chains North of C-9; 1822, Joseph Wampler 9" Beech-S12°E, 7 links 21" Pine-N33°W, 27 links L.C.R.CMartin (L1, P257) 1972; 3/4" pipe L.C.R.CSoltis (L2, P45) 1972; 3/4" pipe Surveys- (L1378, P411-L1352, P415-L1400, P276-L1666, P184) all call for a 3/4" pipe. Survey-Wade-Trim (L1954, P1114) corner not identified.				
Description of corner evidence found and/or method applied in restor	ring or reestablishing com	er.			
B. Description of corner evidence found and/or method applied in restor Found 2" Pipe No witness of record but distances between SW cor and Ctr 1/4 fit well with unrecorded data provided by Spicer Engineering Co. & previous surveys by Ledy.	E-8 Found 3/4" pipe over 5 L.C.R.C. (L1, P257) & NE 107.74' (107.54' Survey (L1666, P184) ENE 107.70' (107.5 SW 52.29' (52.20' n NW 41.80' (42.0' m	5/8" rod over 3/4 (L2, P45) ' m) to SW cor. 4' m) to SW cor n) to top ctr hyd	frame ho . frame h	ouse	
Monument accepted as best evidence of original position.	Monument accepted a	s best evidence	of origina	al positio	on.
C. Description of monument for corner and accessories established to pe	erpetyate locating the pos	ition of the corne	er:		

Set 5/8" rod with remon. cap inside 2" pipe.
SW 94.37' to Nail in West side Power Pole
NW 106.20' to Nail in West side Power Pole
NNW 95.81' to Nail in West side Power Pole
SE 72.15' to Nail in 4" Oak

MAY 1 5 T. T

Set 5/8" rod with remon. cap in monument box.

NW 42.05' to nail & tag in W side light pole

NE 107.54' to SW corner house foundation

ESE 84.60' to nail & tag in NE side 8" Oak

SW 51.18' to top center fire hydrant

	STREET OF MICHAEL
Signed by Alreanie Hedy	Date /c/3//96 = SURVEYOR
Surveyor's Michigan License No. 215/75	No. 21575

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL GUATEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995