APPROVED BY PEER GROUP LIBER 1925 PAGE 1159 P.A. 345 OF 1990 SAGINAW COUNTY REMONUMENTATION SAGINAW COUNT LAND CORNER RECORDATION CERTIFICATE RECORDED & FILED Filing Requirement of Act 74, Mich. P.A. 1970 * S S S For corners in **SURVEY &** Saginaw Corner Code ## PREMONUMENTAT (0 12N _R 3E M-10 Public Land Surve COMMISSION **Property Controlling** S in Section S T R Miscellaneous S R T Register of Deeds Stamp & File Number Property in Sec. S R _ , Recorded Plat _ 5. Private Claims 2 3 July 28 , in a field survey on 19 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 6 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a q Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: M-10 Set post at 40 chains north of M-11, J. Wampler, 1822: 11" Maple S 28° E 23 links. 32" Pine N 5° E 30 links. No record available of restoration or propagation of corner until 1971. J. Martin found 1/2" iron rod in monument box, 1971, L.C.R.C.: L1, P62. D. Hammond found 1/2" iron pipe in monument box, 1978, L.C.R.C.: L4, P223. R. Prevost found 1/2" iron pipe in monument box, 1992; L1837, P1431. Recorded Surveys L1837, P1431: L1615, P1282: L1340, P502: L1338, P482: L1355, P634: L1442, P1025: L1590, P1209: L1563, P1280: L1766, P197. Corner used as common to Sec.25 & 30, T12N, R4E. Recorded surveys calling corner A-10 are: £1413, P815: £1664, P2075. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-10 Found 1/2" rod in monument box. Found recorded witnesses as follows: N.E. 58.14' to face of P.P. (58.4'R). N.W. 76.16' to face of P.P. (75.0'R). S.W. 58.0' to face of street sign (59.1'R). S.E. 61.73' to face P.P. (61.6'R). Same witnesses are on all recordings. Existing monument accepted as the best possible position of original corner. Accepted by Saginaw County Peer Review Group on December 7, 1994. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-10 Set 3" Saginaw County brass cap on 5/8" x 18" rebar over existing 1/2" rod in monument box. ASSESSED OF THE PARTY OF THE PA N 45° W 76.67' to PK nail in west face of utility pole. STEOF MIC S 45° W 69.51' to chiseled "X" in N.E. bolt of base of Sunoco sign, S 45° E 62.15' to PK nail in west face of utility pole. N 45° E 58.42' to PK nail in west face of utility pole. LEDY South 1.22' to Saginaw County Remonumentation cap in monument box (A-10). À

21575 2007-ESSIONAL 21575 21575 21575 21575 28,199x _ Date . Signed by Surveyor's Michigan License No. . FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

PROFESSIONAL