| P.A. 345 OF 1990 SAGINAW COUNTY LAND CORNER RECORDATION CERTIFICATE Ellips Progriement of Act 24 Mich. P.A. 197 | F HOLDAGOS CONTRACTO |
|---|---|
| 8-20-96 SALA Filling Requirement of ACT RECONDEDY FIL | ĽED |
| For comers in Thomas Township LIBER 1997 PAGE 211 Saginaw Located In: Corner Code # | RECOF |
| (County) 1997 JAN 16 P | 2: 43 ORDED ORDED |
| 1. Public Land Survey T 12 N. R 3 E. C-5 MILDRED H. DOD T 12NR 3 E. G-3 REGISTER OF DEL T R SAGINALY COUNTY T R | EDS YER BE |
| 2. Property Controlling STR | Liber 7 Page 47 Register of Deeds Stamp & File Number |
| 4. Lot No, Recorded Plat | |
| 5. Private Claims | A B C D E F G H I J K L |
| | 3 |
| I, Ronald C. Prevost, in a field survey on 1-31, 19_96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in | 4 - 7 - 8 - 9 - 10 - 11 - 12 |
| conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the | 6 -18 -17 -16 -15 -14 -13 |
| Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: | 7 |
| NOTE: Not more than 2 comers, all in the same town and range, may be recorded | 9 |
| on this certificate. | 10 30 29 28 27 26 25 |
| Being rerecorded to correct error of omission. | 12 31 32 34 35 36 |
| A. Description of original monument and accessories and/or subsequent restoration: | 13 |
| L.C.R.C. L1, P155, RR spike - 1972, McKelvey. Recorded surveys L1344 P579, L1349 P799, L1358 P1299, L1446 P682 G-3 Post set by Wampler, 1822, S.C.R.C record 1922 wood stake & c find 1" pipe, Spicer record 1971 find 3/4" pipe. LCRC L1 P121, S.C.R.C. record 1973 find 1" pipe, placed M.B. 1974. Placed a Surveys L1374 P1082, L1446 P694, L1563 P1279, L1783 P1131, L1 B. Description of corner evidence found and/or method applied in restoring or reestablishing co C-5 Found 3/4" pipe in Mon Box SE 146.55 face P Pole (146.55R)(1958 Spicer notes) SE 146.99 Surveyors disc face U Pole (146.58R LCRC L1 P155) NW 50.90 ctr. st. sign post (51.08R LCRC L1 P155) SW 70.67 Surveyors disc in U Pole (70.67R LCRC L1 P155) Location accepted by Peer Review Group 8-20-96 as the best available evidence of the orig G-3 Found boat spike in Mon Box, 1/2 mile measurements N.S.E. & W measurements. Note: 1922 S.C.R.C. wit SE 71.0 to church & 1 | sides fnd 3/4" pipe, 1971. djusting ring 1974. Rec'd 889 P519 mer: inal government corner agree closely with previous |
| Note: 1971 Spicer wit SE 53.55 ctr hyd. now SE 53.69 ctr hyd Review Group 3-6-96 as the best available evidence of the ori | . Location accepted by Peer |
| C. Description of monument for corner and accessories established to perpetuate locating the p | osition of the corner: |
| C-5 Replaced 3/4" pipe with 5/8" bar and Saginaw Co. Re-Mon cap in existing Mon. Box 9-96 S.45°W 70.67 Surveyors disc face Util. Pole N.45°W 50.90 Ctr. st. sign post. S.65°E. 146.99 Surveyors disc face Util Pole N.45°E. 71.47 set nail rt. side 8" Poplar. | |
| G-3 Replaced boat spike with 5/8" rod & Sag. Co. Re-mon cap in ex N.45°W. 40.28 (40.35R) nail & cap SW side T. pole. N.40°E. 62.30 (62.35R) nail & cap SE side P. pole. S.45°E. 48.63 set nail & cap RT. side P.& T. pole. S.40°E. 53.69 (53.55R) ctr. hyd. S.40°E. 118 60 N.W. cor. block fnd'n church. | STATE OF MICHIGATE PREVOST |
| | 7-20-96 To NO. |
| Surveyor's Michigan License No. 24612 - REMONUMENTATION | POFESSIONAL |
| | E BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 |

MAY 1 6 1997

REVISED JAN., REVISED OCT.,