DEC 1 5 1993

Saginaw County Remonumentation

LIBER 1886 PAGE 687

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 6 Page 152

For corners in	•	ŕ	₩ ₇ 🗩
Saginaw	Located In:	Corner Code =##	ACCUST
Public Land Survey Property Controlling	T 12N R 4E T 12N R 4E T R 8 T R R	G-1 H-1	OGROED & FILED I 4 25PH 193 I 4 25PH 193 I A 25PH 193
in Section			· •
3. Miscellaneous Property in Sec.	S T R S T R	· · · · · · · · · · · · · · · · · · ·	 Register of Deeds Stamp & File Number
	, in a field survey on Augus		2 6 5 4 3 2
do hereby certify that under re in lines 1 and 2 above were i	, in a field survey on equirements of P.A. 74, Michigan P.A. in conformance with regulations an ructions of the United States Depar	of 1970, the corner points menti id rules therefore as required i	in the 6 18 17 16 15 14 13
Management or by a decree of above were in conformance w	factors of the office dates began factorists of the Michigan Board of re-established, monumented, re-r	er points mentioned in lines 3, 4 a of Land Surveyors or by a Decre	and 5 8 19 20 21 22 23 24 ee of a
expressed below:	, management of		10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate	corners, all in the same town ar	nd range, may be recorded	11 12 -31 -32 -33 -34 -35 -36
A. Description of original	monument and accessories and	d/or subsequent restoration	

- - G-1 Intersect 32 L. E of standard post by J. Wampler, 1822. Beech 9" N 1" W 25 L. Sugar 16" S 69° E 41 L. No evidence of post or witnesses found.

S.C.R.C. found nail 4-26-73; found bolt spike and replaced with 3/4" iron pipe 7-27-92. Recorded Survey - L. 1600, P. 1613 - 1981.

H-1 Corner not set in original GLO survey. S.C.R.C. found 3/4" Iron bar In mon. box 11.86' W of H-3 - T13N -

R4E on 4-26-73. Corner platted as NE corner of Urbana Park Subdivision. Fits plat occupation S.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found 3/4" iron pipe in mon. box on standard line per S.C.R.C. records. GLO closing to G-13 - T13N - R4E fits record. Monument accepted as the best available evidence of the position of the original corner. Accepted by Saginaw County Peer Group on 9-23-93.

H-1 Found 3/4" iron pipe in mon. box 0.04' N of standard line per S.C.R.C. records at 11.73' W of monumented position at H-13 - T13N - R4E. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner. Accepted by Saginaw County Peer Review Group on 9-30-93.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - G-1 Replace 3/4" iron pipe with Saginaw County 3" brass cap on 5/8" rebar in mon. box.

N 35° E 59.17' to chiseled 'x' on W'ly flange bolt on fire hydrant. N 22° W 78.75' to nail and tag in SW side U.P.

S 55° W 74.25' to nail and tag in SE side U.P.

S 40° E 80.89' to chiseled 'x' on SW of flange bolt of fire hydrant. W 21.80' (m) (21.78' GLO and S.C.R.C.) (21.85' - R) to 3/4" iron pipe in mon. box (G-13 - T13N - R4E).

H-1 Replace 3/4" iron pipe with Saginaw County 3" brass cap on 5/8" rebar in mon. box.

E 11.73' to 3/4" iron pipe in mon. box (H-13 - T13N - R4E). S 22° W 112.86' to NE corner House.

N 10° E 40.52' to chiseled 'x' on W flange bolt on fire hydrant.

N 48° W 157.90' to SE corner House.

S 70° W 123.95' to chiseled 'x' on S. flange bolt fire hydrant.

OF MICHICAN CRAIG W. MCVEAN PROFESSIONAL STABOARD OF 3900 SURVEYOR Surveyor's Michigan License No. _ DARD OF LAND SURVEYOR 39088 REVU