DEC 1 5 1993

Saginaw County Remonumentation

LAND	COHNER	HECO	KDATI	ON CEH	HFIC	AIE
Filina	Requirem	ent of	Act 74	4. Mich.	P.A. 1	970

COMMISSION For corners in

Property in Sec.

Saginaw Located In: Corner Code =## (County) T ..12N. R _4E_ 1. Public Land Survey T_12N_R_4E_ T _____ R ___ _ R Τ_ **Property Controlling** T ___ __ R in Section Miscellaneous _ T _ ___ R _

Т

LIBER 1886 PAGE 684 LIBER 6 Page 149

Register of Deeds Stamp & File Number

_ , Recorded Plat _ 4. Lot No. 5. Private Claims

R

Craig W. McVean August 19 I Craig W. McVean in a field survey on August 19 93 19 93 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

7 8 9 10 11 12

Description of original monument and accessories and/or subsequent restoration:

E-6 Set post - J. Wampler, 1822. Beech 10" S 56° W 10 L. Beech 8" N 85° E 7 L. No evidence of post or witnesses found.

L.C.R.C. - L. 3, P. 78 - 1974 - J. Martin. Recorded Surveys - L. 1589, P. 1518 - 1980; L. 1534, P. 1295 - 1977.

11 record plats fied to corner.

G-6 Set post - J. Wampler, 1822. Beech 11" N 86° W 2.5 L. Sugar 16" S 84° E 21 L. No evidence of post or witnesses found.

L.C.R.C. - L. 1, P. 106 - 1971 - J. Martin. Fits City of Saginaw Survey Map #23. Tie to centerline of

Mackinaw Road to W. 27 record plats tied to corner.

Recorded Surveys L. 1376, P. 451 - 1972; L. 1383, P. 656 - 1972.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-6 Found 3/4" iron pipe in mon. box per L.C.R.C. - L. 3, P. 78. Monument accepted as best available evidence of the position of the original corner. Accepted by Saginaw County Peer Review Group on 9-23-93.

G-6 Found 3/4" iron pipe in mon. box per L.C.R.C. - L. 1, P. 106. Monument accepted as best available evidence of the position of the original corner. Accepted by Saginaw County Peer Review Group on 9-30-93.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6 Replaced 3/4" iron pipe with Saginaw County 3" brass cap on 5/8" rebar in mon. box. N 19° W 136.26' to SE corner of House #2545. N 69° E 66.72' to nail and tag in N side U.P.

S 31° E 131.51' to NW corner garage #2482. S 71° W 143.58' to NW corner garage #2465.

G-6 Replaced 3/4" Iron pipe with Saginaw County 3" brass cap on 5/8" rebar in mon. box.

N 32° E 87.48' to SE corner House #3716. S 30° E 92.28' to NE corner House #3715.

S 39° W 145.44' to NW corner House #4005.

N 50° W 50.77' to chiseled 'x' on N rim water manhole.

N 42.85' (43' P.) to 3/4" pipe in concrete.

OF MICHIGAN CRAIG W. **McVEAN** SURVEYOR

FORM APPROVED BY MICHIGAN SALT

PROFESSIONAL No. 39088

Craix M. Ma Ven Date /

OFESSION IL