NOV 2 1 1997

COMMISSION PERMIT

UBER 2 PAGE 121

REMOUNUMENTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECE	VED FOR RECOR	D
97 S	P-9 AM 8:56	,)
IBFRHO	A PAGE NO. 16	1
RE	METER OF HEFTIS	
SAN	LAC CO. MICHIGAN	

For corners in

Sanilac	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>10N</u> R	12E D - 1
	T R	100.00
2. Property Controlling in Section	S TR S TR	
3. Miscellaneous Property in Sec.	S TR S TR	

Register of Deeds Stamp & File Number

I. Lot No,	Recorded	Plat		
5. Private Claims				

I, John A Milletics , in a field survey on May 21 , 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

		B (C D	E	F (3 H	Ι	J	K	L	ŀ
٠		1			1					· "	
2	2 ├─	6	 5-		4	 - :	3-	— ģ.	-	– į –	_
:	3	<u> </u>		4	_			_			
4	ı	! —	 	\perp	ļ 9—	<u>1</u>	0	_11	_	12	
;	5 -	-		+	-				_		_
•	5 -1	ļ o —	17		6	1	5	14		1 3	-
-	7	-			ļ.,	ļ			_	_	_
8	31	 9		<u> </u>	 21	2	2	 23		_24_	
9		<u> </u>			<u> </u>						_
1	.0 3] 30	29_	1.	8	2	7	2 6	_	 25	-
1	1				ļ			4	\perp	_	
	1	1	32_	 3	3	 —3	4	 —35	_	-36-	
		İ									ĺ

A. Description of original monument and accessories and/or subsequent restoration;

D - 1 GLO NOTES

No No

No Notes Avalible

APPROVED PEER BOARD MEETING

Aug. 18, 1997 JM

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D - 1

N 1/4 Corner Section 5 T10N-R12E

Found Monu Box in Place - removed by Sanilac County Road Comm. during reconstruction of Road - REPLACED using Act 74 as recorded in Liber 1 on Page 385

C. Description of monument for corner and accessories established to perpetuate	e locating the position of the corner:
D - 1	
N 1/4 Corner Section 5 T10N-R12E	Hill Co. Michigally
Monu Box with iron and cap	
N50°E 53.02 feet to a nail in a Power Pole	
S20°E 68.41 feet to the NW Cor of a House	John A. Milletics +
S10°W 36.30 feet to a nail in a Power Pole	Land Surveyor Ro. 26859
N10°W 20.00 feet to a nail in a Mailbox Post	
S10°E 31.35 feet to a nail in a 12" Pine	The state of the s
West2644.19 to the NW Corner Section 5	The second of the second
- 1	Woonal Still
7.14 mm	wwither.
Signed by Aut l'allate	Date Aug 11, 1997
Surveyor's Michigan License No. 25859	