RECEIVED	FOR	RECORD
A Sam College & Earline	1 1 1 1 1	NECONO

The state of the s

REMONUMENTATION & TONY For corner Sin J. M.E. N.T. A.T. O.N.	
For corners In MEN "	

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

94 DEC 16 AM 9: 41

LIBER NO. 2 PAGE NO. 21	
ESTHER LEE	
REGISTER OF DEEDS	
SANILAC CO., MICHIGAN	

_	County) 1 0 190	\overline{c}_{α}	Located In:	Corner Code ##
1.	Public Land Survey	SIUN	т <u>10 ^NR 13 ^E</u>	A - 10
	\sim O N_{II}		T R	
	0		T R	
			T R	<u> </u>
2.	Property Controlling	S	T R	<u> </u>
	in Section	S	T R	
3.	Miscellaneous	s	T R	

Register of Deeds Stamp & File Number

	. Lot No, Recorded Plat	
		*

John A Milletics , in a field survey on . Aug 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

A - 10GLO Notes Set Post Ash 5 S 11 W .13 , Cedar 9 N10W .7

Approved Peer Board Meeting Dec. 16, 1994_ <u>gn</u>

10

11

Act 74 Form - None

Act 132 Form - Liber 4, Page 806

County Surveyor - None

Road Comm -

Drain Comm -

None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

W 1/4 Cor Section 30 T10N-R13E Found 1/2" iron bar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 10

W 1/4 Cor Section 30 TlON-R13E

Found 1/2" Iron Bar

North 33.0' to a 1/2" iron bar

Surveyor's Michigan License No. 25859

East 30.40' to a Wood Fence Post

N83°W 35.28' to a notch in a 36" CMP

N28°W 72.36' to a notch in a 36" CMP



Signed by Date Dec 5, 1994	