	was seed						
	` _	•				·	
	MENT	RTION LIBER	2 PAGE 4		RECEIVED FOR RE	ECORD	
REM	ONUMENTATION NE	LAND CORNE	R RECORDATION CE	RTIFICATE	94 DEC 16 AM 9	. 1.0	
a Siling Requirement of Act 74. Mich. P.A. 1970							
FOLC	Somers APR L	15510.	Campan Carla off		LIBER NO 2 PAGE NESTHER LEE	10	
	Sanilac AF	Min Located in:	Corner Code:		REGISTER OF DEEL SANILAC CO., MICHI)S Gan	
1. P	Public Land Survey	T_10NR_13 E	E - 13		SAMENO COS INCIN	uni.	
		T R					
•		T R T R			,		
2. P		TR					
		T R T R		Dow't	atau at Duada Otaura 9 mil	a Namahan	
		T R		Regi	ster of Deeds Stamp & Fil	e Number	
4 1.	ot No	rded Plat					
		ided Flat			ABCDEFGH	I I K L M	
				•	2 6 5 4 3	2-1-1-1	
				•	4 7 8 9 10	1112	
I, John A Milletics, in a field survey on April 28 19 94 5							
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the							
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							
above	were in conformance with the	e rules of the Michigan Board of tablished, monumented, re-	of Land Surveyors or by a De	cree of a	9		
	essed below:	tabilished, mondinented, te-	nonumented, recovered, r	ouna as	10 30 29 28 27	2625	
NOTE	E: Not more than 4 corne on this certificate.	ers, all in the same town a	nd range, may be record	led	11 12 31 32 33 3	35 36	
					13		
	A. Description of original monument and accessories and/or subsequent restoration: E - 13 GLO Notes Approved Peer Board Meeting						
-	Set Post Ash 12 N 25 W 36, Elm 16 N 61 E Dec. 16, 1994						
	Act 74 Forms Liber 1 Page 97, Liber 1 Page 270						
	Act 132 Forms Liber 1 Page 283, Liber 1 Page 88						
1	Road Comm	Liber 3 Page 14 NONE	Liber 3 Page 514				
	Drain Comm	None					
	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
	E - 13 SW Cor Section 33 T10N-R13E						
Found 5/8" Iron Bar							
	•						
		or corner and accessories	established to perpetuat	e locating the	position of the corner:		
	E - 13 SW Cor Section 33 T10N-R13E						
	Found 5/8" Iron Bar	ç .			William	Michigally	
	· · · · · · · · · · · · · · · · · · ·	2" Iron bar(NW Cor					
	N45°E 56.3 to a nail se Side of a Fence Post S45°E 48.35 to a nail NE Side of a Tele Pole Land Surveyor						
	N45°W 81.80 to a nail SW Side of a Power Pole						
					1/1/1/19	al Sullill	
	11/1	100101		_	· "/////	Willian.	
Signed by Date Dec 6, 1994							
Surveyor's Michigan License No25859 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975							
						REVISED JAN., 1983	