

LAND CORNER RECORDATION CERTIFICATE

94 AUG 12 PM 2: 38

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 1 PAGE NO. 471

For corners in

ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

<u>Sanilac</u> (County)	Located In:	Corner Code =#
1. Public Land Survey	T <u>10</u> N R <u>13</u> E	<u>M - 3</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, John A Millettics, in a field survey on July 6, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

M - 3
 Found 1" Iron Bar 4.0' of centerline of gravel road as recorded in Liber 3 on Page 418 of the Sanilac County Records.

Approved Peer Board Meeting
 Aug. 9, 1994
[Signature]
gm

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M - 3
 SE Cor Section 1 T10N-R13E
 Found 1" Iron Bar

SURVEY & REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M - 3
 SE Cor Section 1 T10N-R13E
 1" Iron Bar
 North 54.75' to a nail on the west side of a Power Pole
 S30°E 43.30' to a stop sign
 S50°W 97.55' to a nail on the SE side of a 6" Poplar
 N10°W 13.60' to the west leg of a road sign
 South 2641.28' to the E 1/4 corner of Section 12

Signed by John A. Millettics
 Surveyor's Michigan License No. 25859

Date July 23, 1994