

REMONUMENTATION

LIBER 1 PAGE 476

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

94 AUG 12 PM 2: 38

For corners in

LIBER NO. 1 PAGE NO. 476  
ESTHER LEE  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

Sanilac (County) Located In: Corner Code ##

1. Public Land Survey	T	10 N	R	13 E	M - 10, M - 11
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Sec.	S		T	R	
	S		T	R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, John A Milletics, in a field survey on July 7, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- M - 10 Found 5/8" Iron bar in gravel road bed
- M - 11 Found 5/8" Iron bar in paved surface

Approved Peer Board Meeting  
Aug. 9, 1994 *[Signature]*  
*[Signature]*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M - 10  
E 1/4 Cor Section 25 T10N-R13E  
Found 5/8" Iron Bar
- M - 11  
SE Cor Section 25 T10N-R13E  
Found 5/8" Iron Bar

SURVEY &  
REMONUMENTATION

SEP 07 1994

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- |   |  |
|---|--|
| M - 10<br>E 1/4 Cor Section 25 T10N-R13E<br>5/8" Iron Bar<br>N80°E 33.00 to a metal fence post<br>S75°E 33.20 to a metal fence post<br>N45°E 40.10 to a metal fence post<br>South 2632.8 to the SE of 25<br>North 2611.82 to the NE of 25 | M - 11<br>SE Cor Section 25 T10N-R13E<br>Monu Box<br>N40°E 60.8 to a nail top of Fence Post<br>N60°E 89.3 to a nail NW side of Power Pole<br>N45°W 51.7 to a nail NE side of a Fence Post<br>S65°W 37.6 to a road sign<br>North 2632.8 to the E 1/4 Cor Section 25 |
|---|--|

Signed by John A Milletics Date July 23, 1994  
Surveyor's Michigan License No. 25859